

Kgc Workshop Pte Ltd (Co.Reg.No:201719986M)

14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Tel: 64510353 /64536279 Fax: 64565140 Email:

joyce@kgcworkshop.com.sg;dj@kgcworkshop.com.sg;lincoln@kgcworkshop.com.sg;pohkin@kgcworkshop.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

| | | | |
|---------------------|-------------------------------|-----------------------|------------|
| Claim Type: | OD (OWN DAMAGE) | Ref. No: | |
| Policy No: | D19MCV0001408 | Date of Loss: | 02/02/2023 |
| Vehicle Reg. No.: | GBE8411U | Driveable? | |
| Driver Age/Info: | | Party At Fault: | UNKNOWN |
| TP Injury Involved? | NO | Third Party Involved? | YES |
| Insured/Claimant: | STARLAND CONSTRUCTION PTE LTD | | |

| | | | |
|-----------------|------------------------|--------------------|---------------|
| Make/Model: | TOYOTA DYNA, 3.0 D (M) | Vehicle Reg. Date: | 31/03/2016 |
| Vehicle Colour: | SILVER | Chassis No: | KDY2318023621 |
| Engine No: | 1KD2591398 | | |
| Odometer: | 195129 KM | | |

*NOT WITHHOLD
1 Rep &
Henry Alan Lim*

| | |
|-------------------------------|-----------------|
| Paint Type: | NO |
| Total Loss? | NO |
| Est. Duration of Repair (day) | <i>7 6 days</i> |

Present Location: **KGC WORKSHOP PTE LTD (AMK)**

| COST OF CLAIMS | Amount |
|---------------------------|-----------------|
| | 3,906.00 |
| Parts | 11.88 |
| Miscellaneous Items | 3,670.00 |
| Labour | 0.00 |
| Paintwork Labour | 0.00 |
| Towing | |
| Gross Total (\$\$) | 7,587.88 |
| + GST 8.00% (\$\$) | 607.03 |
| Nett Amount (\$\$) | 8,194.91 |

This claim is handled by: CHONG POH KIN

REFERENCE DETAILS

Reference: *387*

Part Source: (Last Synchronised: 15 Feb 2023)

Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|-----|-----|--------------------|------------------------------|-------------------|-------|------------------------|
| 1 | 1 | | *Front center panel | 0.00 | 0.00 | <i>By</i> *220.00 F ✓ |
| 2 | 1 | | *Front panel top rubber | <i>Ref</i> 0.00 | 0.00 | *185.00 F ✓ |
| 3 | 1 | | *Front panel top garnish LHS | 0.00 | 0.00 | <i>mit</i> *75.00 F ✓ |
| 4 | 1 | | *Front grille | 0.00 | 0.00 | <i>mit</i> *255.00 F ✓ |
| 5 | 1 | | *Front grille Emblem | 0.00 | 0.00 | <i>mit</i> *40.00 F ✓ |
| 6 | 1 | | *Headlamp RHS | <i>myoma</i> 0.00 | 0.00 | *480.00 F ✓ |
| 7 | 1 | | *Headlamp LHS | <i>L L</i> 0.00 | 0.00 | *480.00 F ✓ |
| 8 | 1 | | *Front Bumper | 0.00 | 0.00 | <i>Ben</i> *245.00 F ✓ |
| 9 | 1 | | *Aircon blower | 0.00 | 0.00 | *385.00 F ? |
| 10 | 1 | | *front dashboard | 0.00 | 0.00 | *450.00 F ? |
| 11 | 1 | | *Clutch set | 0.00 | 0.00 | *425.00 F ? |
| 12 | 1 | <i>by Part No.</i> | *Flywheel bearing | 0.00 | 0.00 | *15.00 F ? |
| 13 | 1 | | *Top clutch pump | 0.00 | 0.00 | *110.00 F ? |
| 14 | 1 | | *Low clutch pump | 0.00 | 0.00 | *95.00 F ? |
| 15 | 1 | | *Front Bumper clips | 0 | 0.00 | <i>Ma</i> *50.00 FS ✓ |
| 16 | 1 | | *front carplate | 0 | 0.00 | <i>Se</i> *50.00 FS X |

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **3,560.00**

+ Margin on L,N Items 10.00% (\$\$) **346.00**

Total Parts (\$\$) 3,906.00

**Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Estimates on Miscellaneous Items

| No | Particulars | Amount |
|-------------------------|----------------------|--------------|
| 1 | OD/TP Case (Insurer) | 11.88 |
| Sub Total (\$\$) | | 11.88 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|---------------------------------|---|----------|-----------------|
| Labour Items | | | |
| 1 | To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts. | New | 700 1,500.00 |
| 2 | To putty and spray paint on all accident damage parts and other accident affected areas | New | 650 1,200.00 |
| 3 | Mechanic Labour to remove gearbox to repair and refit the same | New | 550 500.00 |
| 4 | Mechanic Labour To remove and refit dashboard | New | 250 300.00 |
| 5 | To check wiring system to facilitate repair and refit the same | New | 200 120.00 |
| Gross Labour Cost (\$\$) | | | 3,670.00 |

Kgc Workshop Pte Ltd/GBE8411U/15/02/2023 15:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >