



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/ALLIANZ
Policy No:	SP2002916622-01	Date of Loss:	14/02/2023
Vehicle Reg. No.:	SJA4372B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GAN HOCK SENG		
Driver:	GAN JIAN EN		

Make/Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Vehicle Reg. Date:	03/10/2017
Vehicle Colour:	RED	Chassis No:	KMHD841CMJU542328
Engine No:	G4FGHU620920		
Odometer:	0 KM		<i>NOT WORKING</i>
Paint Type:			<i>1 Day &</i>
Total Loss?	NO		<i>Re-work After Paint</i>
Est. Duration of Repair (day)	0		<i>6 days</i>

Description of Accident/Loss: REFER GIA REPORT ATTACHED.
 Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.
 Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS	Amount
Parts	2,289.10
Miscellaneous Items	40.00
Labour	1,880.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,209.10
Acknowledged by the Insurer	+ GST 8.00% (S\$)
Signature:	336.73
Date:	Nett Amount (S\$)
	4,545.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This claim is handled by: SHARON CHIONG BENG CHOON

REPAIR DETAILS

SJA 4372B

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Feb 2023)
 Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SJA4372B/16/02/2023 10:43
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

OD/Allianz

7041
PF
08
over /

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR RH DOOR	By 0.00	0.00	*680.00 F
2	1		*1 SET REAR RH DOOR FRAME STICKER	Me 0.00	0.00	*28.00 F
3	1		*1 PC REAR RH DOOR INNER RUBBER		0.00	*75.00 F
4	1		*1 PC REAR RH FENDER	By 0.00	0.00	*780.00 F
5	1		*1 PC REAR WINDSCREEN GLASS MOULDING	Me 0.00	0.00	*38.00 F
6	1		*1 PC REAR RH SPORT RIM	De 0.00	0.00	*480.00 F

F=Franchise part.

Sub Total (\$\$) 2,081.00
 + Margin on L,N Items 10.00% (\$\$) 208.10
Total Parts (\$\$) 2,289.10

Cheng Hoe Motor Pte Ltd/SJA4372B/16/02/2023 10:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC REAR WINDSCREEN GLASS SEALANT	Me 40.00
Sub Total (\$\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00
2	REMOVE & REFIX TOP ROOF LINING,SEAT,GARNISH	New	100 120.00
3	REMOVE & REFIX REAR BUMPER,RH TAILLAMP,REAR RH DOOR,TRANSFER DOOR ATTACHMENT,TO CUT,WELD & RENEW REAR RH FENDER AND REALIGN THE SAME	New	700 900.00
4	PUTTY & RESPRAY ON REAR RH FENDER,REAR RH DOOR AND ALL AFFECTED AREAS	New	600.00
5	REMOVE & REFIX REAR RH DOOR GLASS	New	60.00
6	REMOVE & REFIX REAR RH SPORT RIM	New	30.00
7	TO CHECK REAR RH UNDER CARRIAGE & CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	70.00
Gross Labour Cost (\$\$)			1,880.00

Cheng Hoe Motor Pte Ltd/SJA4372B/16/02/2023 10:43. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Good / Fair / Poor / Burnt