

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

SINGAPORE 068897

TEL: 6714 3369

ATTN: Motor Claim Department

Estimate No: **EST2300072**

Date: 15 Feb 2023

Veh Reg No: **SGM6639S**

Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR

Chasis No: RU11114258

Reg. Date: 30/09/2016

Your Ref No: SJW5140G

Claim Type: Third Party

Accident Date: 14/02/2023

Estimate Repair Cost to Vehicle No :SGM6639S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BOOT LID	1,168.00	
2	1 PC REAR BOOT LID LOGO	48.40	
3	1 PC REAR BOOT LID "VEZEL" EMBLEM	45.80	
4	1 PC REAR WINDSCREEN RUBBER	125.00	
5	1 PC REAR BOOT LID LOCK	187.00	
6	1 PC REAR BOOT LID LOCK CHECKER	39.00	
7	1 PC REAR BOOT LID TRIM	215.00	
8	1 PC REAR BOOT LID RUBBER	186.90	
9	1 PC REAR PANEL	495.70	
10	1 PC REAR PANEL TRIM	196.20	
11	1 PC REAR BUMPER	829.60	
12	2 PCS REAR BUMPER SIDE RETAINERS	76.20	
13	1 PC REAR BUZZER	99.70	
14	1 PC REAR RH FENDER GARNISH	189.20	
15	1 PC REAR LOWER COVER	267.90	
16	1 PC REAR EXHAUST PIPE	667.50	
		4,837.10	
	Less 20%	967.42	3,869.68
Special Net			
17	1 PC REAR WINDSCREEN SEALANT	60.00	
18	1 PC REAR WINDSCREEN SEALANT RUBBER	60.00	
19	1 SET REAR BOOT LID TRIM CLIPS	40.00	
20	1 SET REAR PANEL TRIM CLIPS	30.00	
21	1 SET REAR BUMPER CLIPS	60.00	
22	1 SET REAR REVERSE SENSORS	250.00	
23	1 SET REAR RH FENDER GARNISH CLIPS	40.00	
24	1 SET REAR LOWER COVER CLIPS	40.00	
		580.00	580.00
Labour			

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01
SINGAPORE 068897
TEL: 6714 3369
ATTN: Motor Claim Department

Estimate No: EST2300072
Date: 15 Feb 2023
Veh Reg No: SGM6639S
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD 5DR
Chassis No: RU11114258
Reg. Date: 30/09/2016
Your Ref No: SJW5140G

Claim Type: Third Party
Accident Date: 14/02/2023

Estimate Repair Cost to Vehicle No :SGM6639S

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
25	1 TO CHECK WIRING	50.00	
26	1 (REAR) TO REMOVE AND REFIT WINDSCREEN GLASS	120.00	
27	1 TO REMOVE AND REFIT THIRD BRAKE LIGHT	80.00	
28	1 TO REMOVE AND REFIT REAR WINDSCREEN VIDEO CAMERA	80.00	
29	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
30	1 TO REMOVE AND REFIT REAR INNER TRIM	100.00	
31	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
32	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	100.00	
33	1 TO SPRAY PANEL SEALANT	80.00	
34	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	800.00	
35	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,570.00	2,570.00
		Total	S\$ 7,019.68
		Add GST @ 8%	561.57
		Total Amount Payable	<u>S\$ 7,581.25</u>

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FIVE HUNDRED EIGHTY ONE AND CENTS TWENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE