

Date: 14/02/2023

Vehicle No: SMP7128G

Model: HONDA SHUTTLE HYBRID 1.5 CVT

Chassis: GP72004590-2018

Reg. Year: 2019

Third Party Insurer: AIG

Third Party Veh No: SBY25Z

Date of Accident: 10/02/2023

Estimator: TING AN

Surveyor:

*Not Authorized
C/Ping &*

Pressure After Rain

4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Re</i> \$976.90 ✓
2	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Re</i> \$55.20 ✓
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>Re</i> \$45.60 ✓
4	REAR TAILGATE "HONDA" EMBLEM	1		<i>Re</i> \$44.60 ✓
5	REAR TAILGATE INNER TRIM BOARD	1		<i>Re</i> \$356.80 X
6	REAR TAILGATE WEATHERSTRIP	1		<i>Re</i> \$144.40 X
7	REAR TAILGATE INNER LOCK	1		<i>Re</i> \$189.10 ✓
8	REAR WINDSCREEN MOULDING	1		<i>Re</i> \$77.50 ✓
9	REAR BUMPER	1		<i>Re</i> \$783.70 ✓
10	REAR BUMPER TOWING COVER	1		<i>Re</i> \$38.40 ✓
11	REAR BUMPER SIDE BRACKET LH	1		<i>Re</i> \$112.20 X
12	REAR BUMPER SIDE BRACKET RH	1		<i>Re</i> \$112.20 X
13	REAR BUMPER REFLECTOR LH	1		<i>Re</i> \$96.30 X
14	REAR BUMPER REFLECTOR RH	1		<i>Re</i> \$96.30 X
15	REAR END PANEL	1		<i>Re</i> \$447.40 X
16	REAR END PANEL UPPER COVER	1		<i>Re</i> \$129.40 ✓
17	REAR FLOOR PANEL TOOLBOX TRAY	1		<i>Re</i> \$396.60 X
18	REAR FLOOR PANEL TOOLBOX UPPER BOARD	1		<i>Re</i> \$580.20 X
SUB TOTAL				\$4,682.80
LESS 20%				-\$936.56
PARTS TOTAL				\$3,746.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>Re</i> \$80.00 ✓
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>Re</i> \$40.00 X
3	REAR BUMPER CLIPS	1		<i>Re</i> \$50.00 ✓
4	REAR BUMPER REVERSE SENSOR	1		<i>Re</i> \$300.00 ✓
5	REAR END PANEL JOINT SEALANT	1		<i>Re</i> \$100.00 X
6	REAR END PANEL UPPER COVER CLIPS	1		<i>Re</i> \$40.00 X
S/N TOTAL				\$610.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 14/02/2023
Vehicle No: SMP7128G
Model: HONDA SHUTTLE HYBRID 1.5 CVT
Chassis: GP72004590-2018
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SBY25Z
Date of Accident: 10/02/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00	400/
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	\$700.00	400/
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC.	\$150.00	120/
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	50/
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	30/
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	15/
LABOUR TOTAL		\$2,010.00

TING AN	TOTAL	\$6,366.24
---------	--------------	-------------------

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

