



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS3/MSG23001750/Wqy3	
			Date: 16/02/2023	
			Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SCU 9828Z	Veh. Inspected	FBL 2776U
	Policy No.	1002156627	Coverage (\$)	0.00
	Claim No.	299874	Excess (\$)	0.00
	Assign From	JOWYN TAY	Assign Date	15/02/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	16/01/2023	Inspection Date	16/02/2023
	Survey held at	K & T ACCESSORY TRADING PTE LTD BLK 3006 #01-372 UBI ROAD 1 SINGAPORE 408700		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			