

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

PARTS. 1509.21
LAB 170.00
1679.21

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Estimate No: EST1509317

Date: 09 Feb 2023

Policy No: GA606551

Veh Reg No: SMS5153E

Make/Model: NISSAN SERENA 1.2L

HIGHWAY STAR

PREMIUM E-POWER

Chassis No: JN1EBAC27Z0000389

Engine No: HR12129459K

Reg. Date: 28/02/2020

Your Ref No: TP 0223-7259

Claim Type: Third Party

Accident Date: 09/02/2023

TP Veh Reg No: YP7391U

Estimate Repair Cost to Vehicle No :SMS5153E

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
List Price				
1 SIDE MIRROR MOTOR, GLASS LAMP, CAMERA ASSY - RH	1,564.400	1 PC	1,564.40	
2 SIDE MIRROR OUTER COVER (TOP- SPRAY) - RH	112.5000	1 PC	112.50	
			1,676.90	
		Less 10%	167.69	1,509.21
Labour				
3 TO REMOVE, REPLACE SIDE MIRROR - RH	200.0000	1 JOB	200.00	
4 TO RESPRAY PAINT ON SIDE MIRROR COVER - RH	120.0000	1 JOB	120.00	
5 TO RESET & RECALIBRATE SIDE MIRROR CAMERA - RH	300.0000	1 JOB	300.00	
			620.00	620.00
Total				S\$ 2,129.21
Add GST @ 8%				170.34
Total Amount Payable				S\$ 2,299.55

TOTAL: SINGAPORE DOLLAR TWO THOUSAND TWO HUNDRED NINETY NINE AND CENTS FIFTY FIVE ONLY

not authorized
LH
verans
16/3/23
ZL photo taken by
1 day

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE