

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SMY 5821 D
 Chassis No. : JN1JANT32Z0001444
 Engine No. : MR20814663B
 Date of Accident : 09.02.2023

Reference No. : 230209-TPC-JSSM04
 Make/Model : NISSAN / X-TRAIL
 Date : 15.02.2023

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	SCR / R Necessary R	\$ 955.80	\$ 860.22
2	1	Front LH Fender	SCR R Scratched R	\$ 521.40	\$ 469.26
3	1	Front LH Side Mirror Assembly	SCR Necessary R	\$ 1,104.00	\$ 993.60
4	1	Front LH Door	SCR Dented R	\$ 711.00	\$ 639.90
5	1	Front LH Alloy Sports Rim	SCR Scratched /	\$ 699.00	\$ 629.10
6	1	Front LH Wheel Trim Moulding	SCR Scratched /	\$ 267.00	\$ 240.30
				\$ 4,258.20	\$ 3,193.65

Total (Parts): \$ 4,258.20 -25% \$ 3,193.65

Labour Charges

26	To fix & dismantle and remove damaged Front Portions; affected damaged portion.	\$ 600.00	600/-
27	To apply anti rust coat and affected areas	\$ 120.00	30/-
28	To check wiring	\$ 180.00	40/-
29	Welding and cutting of affected panels, including chassis alignment.	\$ 750.00	680/-
30	Spray painting for Front Portions affected parts		
31	Refocusing of the front headlamp		
32	Diagnose ECU system and reset error code.	\$ 120.00	R
33	3D Wheel Alignment		
34	To Apply Waterproofing sealer on Front Support Panels		

Total Labour: \$ 1,770.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 4,963.65 1350

Less 10% \$ 4,467.29

JSSM AUTOSOLUTIONS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

3 days L/S Page 1 = 1610.62
 ≈ 1600

16/2/23

130 pm

S/ 15 km