

*Not Authorized
 L1 Pump @ 3950/-
 Recovery After Paint
 Selayi*

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email:kentsengcarservices@gmail.com

M/s MS First Capital Insurance Limited	DATE	15.02.2023
36 Robinson Road #16-01 City House	CAR NO	SLD 2147 J
S 068877 Tel 65073848 Fax 65073849	MAKE	Mercedes

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : XE 4936 M

Pc	Pcs	WDD2120362B312977	UNIT PRICE	AMOUNT	
1	pc	Rear bumper <i>1558</i>		\$1,641.00	✓
10	pcs	Rear bumper clips		\$60.00	✓
2	pcs	Rear bumper side retainer	\$6.00	\$12.00	✓
2	pcs	Rear bumper side bracket	\$41.00	\$82.00	X
1	pc	Rear bumper lower lip protector	\$77.00	\$77.00	X
1	pc	Rear bumper lower chrome moulding		\$546.00	✓
2	pcs	Rear bumper left side reverse sensor <i>short C234</i>		\$359.00	X
1	pc	Rear bumper reinforcement <i>670</i>	\$264.00	\$1,056.00	211 468
1	pc	Rear bumper tow cover		\$814.00	✓
2	pcs	Rear exhaust chrome cover (LH & RH)		\$68.00	X
1	pc	Rear boot lid number plate garnish	\$352.00	\$704.00	X
2	pcs	Rear boot lid reflector (LH & RH)		\$279.00	X
1	pc	Rear boot lid "E250" emblem	\$440.00	\$880.00	X
1	pc	Rear boot lid "TG-TRONIC" emblem		\$79.00	✓
1	pc	Rear boot lid "Mercedes" logo		\$85.00	✓
1	pc	Rear boot lid top lock		\$125.00	✓
1	pc	Rear end panel		\$376.00	✓
1	pc	Rear end panel top garnish		\$1,539.00	X
8	pcs	Rear end panel top garnish clips		\$136.00	X
2	pcs	Tail lamp (LH & RH) <i>108</i>	\$6.00	\$48.00	X
		Apply anti rust and sealant for accident repaired area.		\$1,408.00	X
		Straightening, repairing and realigning onto the rear affected area, cutting rear end panel, knocking rear spare tyre tank panel, dismantle and replace the above affected parts.		\$150.00	X
		Spray painting for all accident affected parts, rear bumper, rear reinforcement bar, rear end panel, rear boot lid & rear spare tyre tank panel.		\$2,000.00	550/-
		Reprogrammed the error codes after the accident repair works.		\$1,500.00	750/-
		To testing, checking, dismantle & replace rear bumper reverse sensor.		\$250.00	X
		KK Auto Consultants hence notify the Repairer of the following:		\$80.00	80/-
		Total		\$14,419.00	

Susan Lim

KENT SENG CAR SERVICES.

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: