



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : GBK5943P

Make & Model : RENAULT KANGOO

Year of Manufacture : 2010

Chassis No. : VF1FWT8H363804733

Ins Company : GE

Engine No. : K9KF647D096752

Excess : _____

Policy No. : _____

Date of Accident : 07.02.2023

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 10,450.00

Plus/Less 10% \$ 1,045.00

Total of Cost / List \$ 9,405.00

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 350.00

Total Parts Cost (Appendix A) \$ 9,755.00

Labour (Appendix B) \$ 1,080.00

Total Repair Cost \$ 10,835.00

Operation

KELVIN SU TEL:97864236 E:kelvinsukwen@cdge.com.sg
JOHARI TEL:97213705 E:joharibh@sparkcarcare.com
OI SUN PIN TEL: 97288916 E:oisunpin@cdge.com.sg
SOO LEONG KEAT TEL:98328740 E:soolk@cdge.com.sg

*Not authorized
1/ Rep &
Perjury after claim*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Heanem Lkk
Company : _____
Survey conducted on : 20/2/23 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : He Date: 20/2/23

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : GBK5943P Case Owner : KELVIN
 Make & Model : RENAULT KANGOO Year Manufacture : 2010
 Chassis No : VF1FWT8H363804733 Engine No : K9KF647D096752
 Sales Order : _____ Supplier : _____
 Order By : KELVIN Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR	1	<i>B₁</i>	\$2,800.00			✓
2	RHR DOOR	1	<i>B₁</i>	\$2,800.00			✓
3	REAR BUMPER	1	<i>B₂</i>	\$1,200.00			✓
4	REAR BUMPER BRACKET	1		\$600.00			?
5	REVERSE SENSORS	1		\$750.00			?
6	EMBLEM "KANGOO"	1	<i>Mc</i>	\$220.00			✓
7	EMBLEM "MAXI"	1	<i>Mc</i>	\$220.00			✓
8	REAR TRUNK LOCK	1	<i>R</i>	\$560.00			X
9	REAR TRUNK HINGE UPPER	2	<i>R</i>	\$350.00			✓
10	REAR TRUNK HINGE LOWER	2	<i>R</i>	\$350.00			X
11	REAR DOOR WINDOW MOULDING	2	<i>B₂</i>	\$250.00			X
12	ARTWORK	1			<i>Mc</i>	\$ 180.00	<i>1001n</i>
13	STICKER "70KM/H"	1			<i>Mc</i>	\$ 30.00	<i>125n-</i>
14	STICKER "5 PAX"	1			<i>Mc</i>	\$ 30.00	<i>125n</i>
15	SEALANT	1			<i>Mc</i>	\$ 40.00	✓
16	NO.PLATE EMBROSS WHITE WORDING	1			<i>B₂</i>	\$ 35.00	X
17	NO.PLATE CASING	1			<i>B₂</i>	\$ 35.00	X
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

