



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : GBK5943PMake & Model : RENAULT KANGOOYear of Manufacture : 2010Chassis No. : VF1FWT8H363804733Ins Company : GEEngine No. : K9KF647D096752

Excess : _____

Policy No. : _____

Date of Accident : 07.02.2023

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : KELVIN

Signature : _____

Parts (a) Cost / List Price Items \$ 10,450.00Plus/Less 10% \$ 1,045.00Total of Cost / List \$ 9,405.00

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 350.00**Total Parts Cost (Appendix A) \$ 9,755.00****Labour (Appendix B) \$ 1,080.00****Total Repair Cost \$ 10,835.00****Operation**

KELVIN SU TEL:97864236 E:kelvinsukwen@cdge.com.sg

JOHARI TEL:97213705 E:joharibh@sparkcarcare.com

OI SUN PIN TEL: 97288916 E: oisunpin@cdge.com.sg

SOO LEONG KEAT TEL:98328740 E:soolk@cdge.com.sg

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : GBK5943P Case Owner : KELVIN
 Make & Model : RENAULT KANGOO Year Manufacture : 2010
 Chassis No : VF1FWT8H363804733 Engine No : K9KF647D096752
 Sales Order : _____ Supplier : _____
 Order By : KELVIN Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR	1		\$2,800.00			
2	RHR DOOR	1		\$2,800.00			
3	REAR BUMPER	1		\$1,200.00			
4	REAR BUMPER BRACKET	1		\$600.00			
5	REVERSE SENSORS	1		\$750.00			
6	EMBLEM "KANGOO"	1		\$220.00			
7	EMBLEM "MAXI"	1		\$220.00			
8	REAR TRUNK LOCK	1		\$560.00			
9	REAR TRUNK HINGE UPPER	2		\$350.00			
10	REAR TRUNK HINGE LOWER	2		\$350.00			
11	REAR DOOR WINDOW MOULDING	2		\$250.00			
12	ARTWORK	1				\$ 180.00	
13	STICKER "70KM/H"	1				\$ 30.00	
14	STICKER "5 PAX"	1				\$ 30.00	
15	SEALANT	1				\$ 40.00	
16	NO.PLATE EMBROSS WHITE WORDING	1				\$ 35.00	
17	NO.PLATE CASING	1				\$ 35.00	
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

