



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

TP Liberty.

Veron.

Vehicle No: QWIE3020E

Make/Model: H/ AVANTE

CHASSIS NO: KMH-LN41ETNU278167

INDEPENDENT SURVEYOR
☒ DIRECT SETTLEMENT

Date: 16.2.23

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1	1	FRONT BUMPER	Del'd	✓		\$ 546.00
2	1	FRONT BUMPER CLIP R/L	new	✓	30	\$ 55.00
3	1	FRONT FOW COVER	Missing	✓		\$ 11.70
4	2	FRONT BUMPER RETAINER L/R	RH 2nd	✓	28	\$ 56.00
5	1	FRONT BUMPER LOGO (H)	new	✓		\$ 44.00
6	1	FRONT RADIATOR GRILLE	new	✓		\$ 299.60
7	1	FRONT BUMPER LOWER GRILLE	new	✓		\$ 127.30
8	1	FRONT LOWER BUMPER	Del'd	✓		\$ 107.30
9	1	FRONT BUMPER LOWER SKIRT (BLK)	new	✓	8/1	\$ 680.00
10	1	FRONT BUMPER RE-INFORCEMENT	Del'd	✓	A8	\$ 695.80
11	1	FRONT BUMPER SPOILER	new	✓		\$ 110.70
12	2	FRONT BUMPER FOG LAMP COVER RH/LH	new	X		\$ 113.70
13	1	RH FRONT HEAD LAMP	new	✓		\$ 1756.40
14	1	RH FRONT HEAD LAMP LOWER BRACKET	new	X		NA
15	1	FRONT BONNET	new	X		\$ 2253.80
16	1	FRONT BONNET HEAD SHIELD	new	X		\$ 97.80
17	1	FRONT BONNET HEAD SHIELD CLIP R/L	new	X		\$ 50.00
18	1	FRONT SUPPORT DAMPER	new	X		949.30
19	1	FRONT ALLOY CONDENSER	new	X		\$ 745.10
20	1	FRONT RADIATOR	new	X		\$ 637.00

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No: 2N123000E

Make/Model: HYUNDAI

CHASSIS NO: _____

☐	INDEPENDENT SURVEYOR
☒	DIRECT SETTLEMENT

Date: 16.2.23

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	MARKING	UNIT \$	AMOUNT (\$S)
1	1	WIPER WASHWATER TANK <i>new</i>	x		89.40.
2	1	RA FRONT FENDER <i>Buckhead</i>	✓	D27	\$1289.10
3	1	RA FRONT FENDER INNER BAHND <i>new</i>	x		195.80
4	1	FENDER INNER BAHND CLIP <i>new</i>	x		30.
5	1	FRONT BONNET LOCK <i>new</i>	x		\$130.60
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					

4768.20
less 20% : 3815.36

SN: 500

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No: 2NE3020E

Make/Model: H/AUANTE

CHASSIS NO: _____

Date: _____

INDEPENDENT SURVEYOR

DIRECT SETTLEMENT

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1		DANU BZAY		400	1500
2					
3		SPRAY PAINT		600	1500
4					
5		RUST PROOF	1060	30	100
6					
7		WIRING CHECK		30	100
8					
9		TO REMOVE/REFIX RADIATOR/ALCANDANER		*	280
10					
11		COOLANT		*	100
12					
13		A/C GAS		*	80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

REMARKS: Signature:

NO OF DAYS: _____

AGREED FIGURE/LUMP SUM: _____

SURVEYOR NAME

EMAIL ADD: _____

CONTACT: _____

Admin Lij

h/s 16/02/23.

04 Days.

total: 537536

h/s: 4.3K