

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|----------------|-------|---------------------|--|
| | STRIDES AUTOMO | OTIVE SERVICES PTE LTD | | Ref: | CS/SMR23001764/Rqy3 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 7705 | | Date: | 16/02/2023 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SG 5818M | Veh. Inspected | | SLK 9936R | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| | Assign From | ASHLENE LEE | Assign Date | | 16/02/2023 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 14/02/2023 | Inspection Dat | е | 17/02/2023 | |
| | Survey held at | 5 Soon Lee Street #01-60, Pioneer Point | | | | |
| | Repairer | CHENG AUTO BODYWORKS | | | | |
| 5a. | a. Remarks | | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | |