



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD
10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983
ATTN: OH VALE

Ref: CS/HSB23001766/Sqp3m4

Date: 28/04/2023

Code: HSB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8657C	Veh. Inspected	SJX 7936J
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S3M04JA8	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	16/02/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053ZEE106180856	Colour	SILVER
Odometer	147972 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65R15	YOKOHAMA	5 mm
L/H Rear Tyre	195/65R15	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/02/2023	Inspection Date	20/02/2023
Survey held at	THE WHEELERS AUTO SERVICES PTE LTD 2 KAKI BUKIT AVENUE 2, #-1-14, KAKI BUKIT AUTOHUB, SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------