

Vehicle No: SJX7936J
Make/Model: TOYOTA ALTIS
Chassis No: MR053ZEE106180856

QTY	Description	Marking	Unit \$	Amount (\$\$)
PARTS LIST				
20	Front Bumper	CRA		\$792.40
	Front Bumper Clips	Nee		\$5.50
	Front Bumper Bracket	CRA		\$79.70
	Front Grille	CRA		\$477.40
	Front Bumper Lower Grille	CRA		\$154.90
	Head Lamp	CRA		\$784.70
	Front fog lamp cover	CRA		\$88.60
	Front fog lamp	CRA		\$466.00
	Front fender	Dent		\$937.30
	Front fender inner liner	CVT		\$235.60
	Front bumper reinforcement	Dent R		
	Front bumper reinforcement foam	X CVT		
	Windscreen water tank	Dent		\$192.50
	Windscreen water pump	CRA		\$220.40
	ABS Pump	Faulty		\$2,180.30
	Front support panel	Dent		\$1,082.40
	Aircon Pipe	Dent		\$480.00
SPECIAL NETT ITEMS				

690
20
280
130
300
60
260
240
90
85
120
XCVT
160

$$P = 2514.70$$

$$25\% = 628.67$$

$$= 1886.03$$



WHEELERS
THE HYBRID WORKSHOP

2 Kaki Bukit Ave 2 @ AutoHub #01-14
Singapore 417921
Tel: 9128 2282
Email: services@thewheelersauto.com

Vehicle No: SJX7936J
Make/Model: TOYOTA ALTIS
Chassis No: MR053ZEE106180856

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	ADJUSTMENT
	LABOUR		
1	Panel beating	\$700	600
2	Spray Paint	\$700	600
	Aircan pipe labour		40
	Reset ABS code		40
	ABS pump labour		60 XNN
	4 days L/S 20/2/23 5.30pm		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Remarks
NO.OF DAYS:
SURVEYOR NAME:
EMAIL ADD:
AGRRD FIGURE/LUMPSUM:

1st Inspection Date:

Supplementary/additonal Date:

After Paint Date:

1st Am

T = 3166.03

N₀ = 633.20

= 2532.82

≈ 2550