

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300073
Date: 16 Feb 2023
Policy No: D-23100460MFQC/69
Veh Reg No: SMM2784K
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3X01178085
Reg. Date: 25/06/2019
Your Ref No: -

Claim Type: Own Damage
Accident Date: 13/02/2023

Estimate Repair Cost to Vehicle No :SMM2784K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC FRT BONNET	999.70	
2	2 PCS FRT BONNET HINGE	167.40	
3	1 PC FRT BONNET TRIM	304.00	
4	1 PC FRT BONNET LOCK	146.80	
5	1 PC FRT BONNET PANEL	162.30	
6	1 PC FRT BONNET LOCK CABLE	91.40	
7	1 PC FRT WIPER PANEL TRIM	767.60	
8	2 PCS FRT WIPER PANEL LH SIDE TRIM	153.80	
9	1 PC FRT FENDER LH	827.50	
10	1 PC FRT FENDER COWLING LH	222.80	
11	1 PC FRT FENDER BRACKET LH	55.50	
12	1 PC FRT LH WHEEL HOUSING	563.30	
13	1 PC FRT SUPPORT PANEL	1,057.20	
14	1 PC FRT SUPPORT PANEL TRIM	296.50	
15	1 PC FRT HEADLAMP RH	1,393.40	
16	1 PC HEADLAMP LH	1,393.40	
17	2 PCS FRT HEADLAMP PANEL	370.40	
18	1 PC FRT GRILLE	415.60	
19	1 PC FRT GRILLE RUBBER	39.50	
20	1 PC FRT GRILLE EMBLEM	80.60	
21	1 PC FRT GRILLE EMBLEM BASE	175.00	
22	2 PCS FRT GRILLE MOULDING	128.20	
23	1 PC FRT BUMPER	533.90	
24	1 PC FRT BUMPER REINFORCEMENT	432.50	
25	2 PCS FRT BUMPER SIDE RETAINERS	217.40	
26	1 PC FRT BUMPER FOG LAMP RH	308.60	
27	1 PC FRT BUMPER FOG LAMP COVER RH	90.50	
28	1 PC FRT BUMPER FOG LAMP LH	308.60	
29	1 PC FRT BUMPER FOG LAMP COVER LH	90.50	
30	2 PCS FRT BUMPER SIDE COVER	157.40	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
 16 RAFFLES QUAY
 #42-01 HONG LEONG BUILDING
 SINGAPORE 048581
TEL: 65073848 **FAX:** 65073849
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2300073
Date: 16 Feb 2023
Policy No: D-23100460MFQC/69
Veh Reg No: SMM2784K
Make/Model: TOYOTA VIOS 1.5E
 AUTO
Chasis No: MR2B23F3X01178085
Reg. Date: 25/06/2019
Your Ref No: -

Claim Type: Own Damage
Accident Date: 13/02/2023

Estimate Repair Cost to Vehicle No :SMM2784K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
31	1 PC FRT BUMPER GRILLE	384.90	
32	1 PC FRT AIR CONDENSER	1,702.40	
33	1 PC FRT AIR CONDENSER TRIM LH	92.80	
34	1 PC FRT AIR CON RECEIVER PIPE	299.40	
35	1 PC FRT AIR CON DISCHARGE PIPE	355.10	
36	1 PC FRT AIR CON LIQUID PIPE	530.30	
37	1 PC AIR CON SUCTION PIPE	427.70	
38	1 PC FRT AIRCON CONDENSER LH TOP TRIM	86.20	
39	1 PC FRT AIRCON CONDENSER LH BOTTOM TRIM	69.90	
40	1 PC FRT AIRCON CONDENSER RH TOP TRIM	86.20	
41	1 PC FRT AIRCON CONDENSER RH BOTTOM TRIM	69.90	
42	1 PC FRT RADIATOR	2,224.10	
43	1 PC FRT RADIATOR FAN	260.70	
44	1 PC FRT RADIATOR FAN MOTOR	675.30	
45	1 PC FRT RADIATOR FAN MOTOR COWLIN	286.80	
46	1 PC FRT RADIATOR TOP HOSE	55.80	
47	1 PC FRT RADIATOR BOTTOM HOSE	49.00	
48	1 PC FRT RADIATOR UNDER COVER RH	236.60	
49	1 PC FRT RADIATOR UNDER COVER LH	236.60	
50	1 PC FRT RADIATOR UNDER COVER (CENTRE)	199.80	
51	1 PC FRT AIR CLEANER ASSY	1,169.80	
52	1 PC FRT AIR CLEANER JOINT HOSE	80.30	
53	1 PC FRT AIR CLEANER OUTLET DUCT	75.90	
54	1 PC FRT HORN	184.20	
		21,791.00	
		Less 25%	5,447.75
			16,343.36
	Special Net		
55	1 PC FRT BONNET "617" STICKER	35.00	
56	1 SET FRT BONNET TRIM CLIPS	40.00	
57	1 SET FRT FENDER COWLING CLIPS LH	40.00	
58	1 PC FRT SUPPORT PANEL TRIM CLIPS	40.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department \ Motor Claim

Estimate No: **EST2300073**
Date: 16 Feb 2023
Policy No: D-23100460MFQC/69
Veh Reg No: **SMM2784K**
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3X01178085
Reg. Date: 25/06/2019
Your Ref No: -

Claim Type: Own Damage
Accident Date: 13/02/2023

Estimate Repair Cost to Vehicle No :SMM2784K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
59	1 SET FRT GRILLE CLIPS	30.00	
60	1 PC FRT NUMBER PLATE	50.00	
61	1 PC FRT "L" PLATE BRACKET	70.00	
62	1 PC FRT "L" PLATE	50.00	
63	1 SET FRT BUMPER GRILLE CLIPS	40.00	
64	1 SET FRT BUMPER CLIPS	40.00	
65	1 SET FRT AIR CONDENSER TRIM CLIPS LH	30.00	
66	1 PC FRT AIRCON CONDENSER TRIM CLIPS	40.00	
		505.00	505.00
	Labour		
67	1 TO CHECK WIRING	50.00	
68	1 TO REMOVE AND REFIT AIRCON GAS	120.00	
69	1 TO REMOVE AND REFIT UNDERCARRIAGE	650.00	
70	1 TO CHECK WHEEL ALIGNMENT	120.00	
71	1 TO TOWING	60.00	
72	1 TO SPRAY PANEL SEALANT	100.00	
73	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,400.00	
74	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00	
		4,300.00	4,300.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Own Damage
Accident Date: 13/02/2023

Estimate No: EST2300073
Date: 16 Feb 2023
Policy No: D-23100460MFQC/69
Veh Reg No: SMM2784K
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3X01178085
Reg. Date: 25/06/2019
Your Ref No: -

Estimate Repair Cost to Vehicle No :SMM2784K

Quantity	Description	List Price S\$	Amount S\$
		Total	S\$ 21,148.36
		Add GST @ 8%	1,691.87
		Total Amount Payable	S\$ 22,840.23

TOTAL: SINGAPORE DOLLAR TWENTY TWO THOUSAND EIGHT HUNDRED FORTY AND CENTS TWENTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE