

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS23001785/ANY3Q2**Date:** 05/07/2023**REFERENCE****Handling Insurer:** Allianz Insurance Singapore Pte. Ltd.**Policy No:****Claimant Vehicle No :** SJP8861B**Insured Vehicle No :** SKW7018C**Date of Loss:** 22/01/2023**Nature of Claim:** TP**Claim No:** 2023 32004956KC**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SJP8861B**Make & Model:** BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)**Engine No:** 11037692N52B25AF**Reg. Date:** 28/02/2011 (Man. Year: 2011)**Chassis No:** WBAFP320X0C864408**Colour:** Blue**Odometer:** 168593 km**Engine Capacity:** 2497 cc**Market Value/New Car****Price:** N/A**Sum Insured (\$\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes **Engine Modification:**No **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 255/35 R20**Rear Tyre Size:** 255/35 R20**Front Left Side:** Michelin 6 mm**Rear Left Side:** Michelin 6 mm**Front Right Side:** Michelin 6 mm**Rear Right Side:** Michelin 6 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,595.62	3,462.75	1,132.87	24.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	900.00	1,650.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,145.62	4,362.75	2,782.87	38.95
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	7,145.62	3,500.00	3,645.62	51.02
Global Sum Settlement (\$\$)		0.00		

INSPECTION**Date of Assignment:** 16/02/2023**Date Inspected:** 06/03/2023 **Inspected At:**Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki
Bukit
Singapore 417883**Estimated Period of Repair:** 4.0 days**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2023)
Parts:	143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP8861B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	1,800.00 FL	*1,600.00 FL
2	1		*FRONT FENDER SIDE GARNISH RH	Cracked	35.00 FL	*35.00 FL
3	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	150.00 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	2.50 FL	*- FL
5	1		*FRONT DOOR RH	Dented	1,965.00 FL	*1,810.00 FL
6	1		*FRONT DOOR GLASS MOULDING RH	Not Necessary	165.00 FL	*- FL
7	1		*FRONT DOOR INNER WEATHERSTRIP RH	Necessary	200.00 FL	*200.00 FL
8	1		*FRONT DOOR INNER TOP RUBBER	Not Necessary	90.00 FL	*- FL
9	1		*FRONT DOOR TOP HINGE	Not Necessary	85.00 FL	*- FL
10	1		*FRONT DOOR LOWER HINGE	Not Necessary	85.00 FL	*- FL
11	1		*FRONT DOOR STOPPER	Not Necessary	110.00 FL	*- FL
12	1		*FRONT FENDER INNER TRIM	Not Necessary	150.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,837.50	3,645.00
- List Item Discount on L Items 5.00/5.00% (S\$)	241.88	182.25
Total Parts (S\$)	4,595.62	3,462.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE ,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
2	RESPRAY PAINTING	New	1,000.00	400.00
3	REMOVE & REINSTALL DOOR GLASS	New	150.00	60.00
4	TUFF KOTE	New	200.00	40.00
Gross Labour Cost (\$\$)			2,550.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >