I. E. ASS. FEO. BY: ASSIGNMENT 5MG 2703B. Yr Regn: 20 19, Feb. From: Date: Veh No: Type (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: OD / TF/WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or Honda HRV To Inspect Vehicle No: Make: Rown. at Worlshop m/s Insured / Std / NI / NA Colour 70525 T/Radio: Insured / Std / NI / NA Sp.Reading insured Eng/No: JHMR41810JX201078 Policy No. C/No: Gen. Cond. Good / Fair / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Make of Veh: Modi: Nil / S/Rim / STD A/Rim or F: 215/60816. Tyre Size: (Policy Condition) Remark The veh had commenced its O/S BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO/YOKO or Bal. or Market Value: Front IDAC Accident Rport: Consistent?: Yes or No R/Bal. R/Bal. GIA / PR Seen: Consistent?: Yes or No L/Bal. L/Bal. Est. Repairs: Res.: Yes or No D.O.A. days Succes 3 Val.: Yes or No Lum Sum: Survey held at Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction OD Allianz. MV: 881c PV:29.1K Nett: 58-91 Date/Time, File Pass to? : Preli. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: : Site Insp (\$ _8 + RS.__8I Interview (\$ Photos Report Formet : Tech. Invs 🔅 Choero

Success United Pte Ltd (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

Ref. No: SU230037 Date of Loss: 14/02/2023 Driveable? Party At Fault: UNKNOWN Third Party Involved? YES YAU Contact No: +6596862197 YAU
Driveable? Party At Fault: UNKNOWN Third Party Involved? YES YAU Contact No: +6596862197
Party At Fault: UNKNOWN Third Party Involved? YES YAU Contact No: +6596862197
Third Party Involved? YES YAU Contact No: +6596862197
YAU Contact No: +6596862197
YAU
-V, 1.5 DX CVT (A) Vehicle Reg. Date: 14/02/2019
Chassis No: JHMRU1810JX201078

Paint Type.

Total Loss?

NO

Est. Duration of Repair (day) 8

Description of Accident/Loss REFER TO SKETCH PLAN.

Present Location:

SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		9,492.70
Miscellaneous Items		0.00
Labour		1,280.00
Paintwork Labour		1,350.00
Towing		0.00
	Calculated Gross Total (S\$)	12,122.70
	- Excess (S\$)	500.00
	(S\$)	11,622.70
	+ GST 8.00% (S\$)	929.82
	Nett Amount (S\$)	12,552.52

This claim is handled by: TAN WEI NI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 16 Feb 2023)

Parts: N/A HONDA HR-V 1.5 DX CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)
Print Code: Success United Pte Ltd/SMG2703B/16/02/2023 18:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers

with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

	imates on F Qty Part No.	Particulars	%Disc	%Depr	Amount
No.	Qty Part No.		0.00	0.00	*420.00 F
1	1	FROM BOME	0.00	0.00	*76.00 F
2	2		0.00	0.00	*25.00 F &
3	1		0.00	0.00	*90.00 F
4	1		0.00	0.00	*80.00 F -
5	1	*Frt Bonnet Lock bracket	0.00	0.00	*95.00 F
6	1		0.00	0.00	*440.00 F 200
7	2	*Frt Fender L/R RH Buckles *Frt Fender Guard RH Ne ~	0.00	0.00	*95.00 F
8	1		0.00	0.00	*395.00 F
9	1		0	0.00	*30.00 FS
10	1		0.00	0.00	*30.00 F 🤻 👶
11	2	Fit Bumper olde Helder Ell	0.00	0.00	*60.00 F
12	2	Fre Bulliper Bracket Lit	0.00	0.00	*20.00 F /
13	1	*Frt Bumper Tow Hook Cover	0.00	0.00	*380.00 F
14	1	*Frt Lower Bumper *Frt Bumper Lower Air Grille	0.00	0.00	*78.00 F
15	1		0.00	0.00	*70 .00 F- 35
16	2	7111 03111111	0.00	0.00	*220.00 F
17	1	*Frt Grille Base	0.00	0.00	*190.00 F
18	1	*Frt Grille Chrome	0.00	0.00	*25.00 F
19	1	Tit Horida logo	0.00	0.00	*250.00 F
20	1		0.00	0.00	*50.00 F
21	1	*Horn ?	0.00	0.00	*1,900.00 F
22	2	*Frt Headlamp L/R Could	0.00	0.00	*360.00 F
23	1	*Radiator Support Panel Assy	0.00	0.00	*750.00 F 👩
24	1	*Radiator ?	0.00	0.00	*65.00 F
25	1	Madiator Support top	0.00	0.00	*30.00 FS -
26	1	*Radiator support top cover garnish clips	0.00	0.00	*35.00 F
27	1	*Radiator Spare Tank *Padiator Lower Hose MC N	0.00	0.00	*25.00 F *
28	1	Radiator Lower Floor	0.00	0.00	*350.00 F ?
29	1	*Radiator Auxillary Fan Assy *Aircon condenser auxillary Fan Assy	0.00	0.00	*380.00 F
30	1		0.00	0.00	*150.00 F -
31	1	*Aircon Discharge Hose	0.00	0.00	*165.00 F -+
32	1	All Coll Discharge Trees	0.00	0.00	*55.00 F 了
33		All littake duct	0.00	0.00	*50.00 F .7
34		All duct	0.00	0.00	*120.00 F.
35		*Air cleaner Housing NC N	0.00		*190.00 F 🚜
36		*Wiper Garnish assy	0		*30.00 FS 🗜
37		*Wiper Garnish Clips Ne ~	0.00		*18.00 F
38	1	*Battery terminal cover	0.00		*150.00 F -
39		*Engine mouting RH	0.00		*180.00 F +
40	1	*Engine mouting LH	0.00		*90.00 F 4
41		*Engine mouting Rear	0.00		*25.00 F 🤼
42		*Radiator top hose *Aircon Condenser	0.00		*360.00 F
43			0.00		*45.00 FS -
44	1 1	*Frt number plate with frame		A STATE OF THE STA	

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Esti	mates	on	la	bour
LOLI	lialos	OII	L. C4	DOGI

No	Particulars	Lab.Type	Amount	
Pair	ntwork Labour		1,200.00	Init
1	To putty & respray painting on bonnet, bumper, support panel, 2pc fender, fender guard RH, frt door RH.			
2	To remove, replace engine mounting.	New	150.00	x
Lab	our Items		1,000.00	802
3	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New		
4	To remove, rearrange electrical wirings, check lighting.	New	100.00	
5	To remove, replace radiator & aircon parts, vacuum & refill gas.	New	180.00	120
	Gross Labou	r Cost (S\$)	2,630.00	

Success United Pte Ltd/SMG2703B/16/02/2023 18:01. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Ly P/P 17/02/23.

Not Authorized

07 Days

Excess: \$500.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	145B
Vehicle Details	
Vehicle No.:	SMG2703B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2023
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	L15B5671080
Chassis No.:	JHMRU1810JX201078
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,962.00
Original Registration Date:	14 Feb 2019
First Registration Date:	14 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$19,962.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Feb 2029
PARF Rebate Amount:	\$14,971.00
Intended COE Rebate Details	· · · · · · · · · · · · · · · · · · ·
COE Expiry Date:	13 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$14,105.00
Total Rebate Amount:	\$29,076.00

The information contained herein is correct as at 20 Feb 2023

Resources

Forum



Compare 🙆

Articles Insurance **Products** Sell My Car Directory Rental Cars **New Cars** Used Cars

