

Kang Car Repairers Pte Ltd

I Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

TEL: 6714 3369

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 09/02/2023

Estimate No: EST2300075

Date: 16 Feb 2023

Veh Reg No: SJT3675J

Make/Model: TOYOTA VIOS E AUTO

Chasis No: MR053HY9305131652

Reg. Date: 05/10/2009

Your Ref No: SNB5224L

Estimate Repair Cost to Vehicle No :SJT3675J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
List Price			
1	1 PC REAR BUMPER	567.10	
2	2 PCS REAR BUMPER SIDE RETAINERS	372.80	
3	2 PCS REAR BUMPER SMALL RETAINERS	136.80	
4	1 PC REAR PANEL	680.10	
5	1 PC REAR PANEL TRIM	232.00	
6	1 PC REAR BOOT LID	758.70	
7	1 PC REAR BOOT LID "VIOS" EMBLEM	44.20	
8	1 PC REAR BOOT LID LOGO	51.10	
9	1 PC REAR BOOT LID "E" EMBLEM	36.80	
10	1 PC REAR BOOTLID "9" EMBLEM	36.80	
11	1 PC REAR BOOTLID "LIMITED" EMBLEM	48.50	
12	1 PC REAR BOOT LID LOCK	295.50	
13	1 PC REAR BOOT LID LOCK CHECKER	29.90	
14	1 PC REAR BOOT LID RUBBER	196.50	
15	1 PC REAR TAIL LAMP RH	357.20	
16	1 PC REAR TAIL LAMP LH	357.20	
		4,201.20	
	Less 25%	1,050.30	3,150.94
Special Net			
17	1 SET REAR REVERSE SENSORS	250.00	
18	1 SET REAR BUMPER CLIPS	40.00	
19	1 SET REAR PANEL TRIM CLIPS	30.00	
20	1 PC REAR NUMBER PLATE	50.00	
		370.00	370.00
Labour			
21	1 TO CHECK WIRING	50.00	
22	1 TO REMOVE AND REFIT REAR INNER TRIM	100.00	
23	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
24	1 TO SPRAY PANEL SEALANT	80.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01
SINGAPORE 068897
TEL: 6714 3369
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/02/2023

Estimate No: EST2300075
Date: 16 Feb 2023
Veh Reg No: SJT3675J
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR053HY9305131652
Reg. Date: 05/10/2009
Your Ref No: SNB5224L


Estimate Repair Cost to Vehicle No :SJT3675J

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
25	1 TO SPRAY PAINTING DAMAGED PORTION, INCLUDING SUPPLY OF PAINT MATERIALS SUCH AS MASKING TAPE, SAND PAPERS, PRIMER, POLISHING COMPOUND AND CHEMICAL ETC.	1,200.00	
26	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00	
		2,510.00	2,510.00
		Total	S\$ 6,030.94
		Add GST @ 8%	482.48
		Total Amount Payable	<u>S\$ 6,513.42</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED THIRTEEN AND CENTS FORTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE