



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9129B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
4	RETAINER, FR FENDER (SN)	NECESSARY	59.20	59.20
10	CLIP, PIN HOLD (SN)	NECESSARY	22.00	22.00
1	ABSORBER, FR BUMPER (SN)	NOT NECESSARY	134.40	-
1	ABSORBER, FR BUMPER (SN)	NOT NECESSARY	119.10	-
1	ABSORBER, BUMPER (SN)	NOT NECESSARY	119.10	-
1	REINFORCEMENT, FR (SN)	NOT NECESSARY	883.30	-
1	RETAINER, FR BUMPER (SN)	NOT NECESSARY	119.50	-
1	RETAINER, FR BUMPER (SN)	NOT NECESSARY	119.50	-
2	BRACKET, RR BUMPER (SN)	NOT NECESSARY	18.60	-
1	COVER, FR BUMPER (SN)	SCRATCHED	1,106.30	1,106.30
1	GRILLE, RADIATOR (SN)	CRACKED	244.40	244.40
1	GRILLE, RADIATOR (SN)	DEFORMED	133.60	133.60
1	MOULDING, RADIATOR (SN)	DEFORMED	104.00	104.00
1	COVER, FR BUMPER (SN)	SCRATCHED	48.80	48.80
1	MOULDING, RADIATOR (SN)	NOT NECESSARY	104.00	-
1	COVER, FR BUMPER (SN)	NOT NECESSARY	48.80	-
1	GARNISH, FR BUMPER (SN)	SCRATCHED	202.70	202.70
1	GARNISH, FR BUMPER (SN)	SCRATCHED	269.40	269.40
1	BRACKET, FR BUMPER (SN)	NOT NECESSARY	143.00	-
1	GRILLE SUB-ASSY (SN)	NOT NECESSARY	1,207.30	-
1	SEAL, HOOD TO (SN)	NECESSARY	117.00	117.00
1	MEMBER SUB-ASSY, FR (SN)	NOT NECESSARY	343.10	-
1	EMBLEM, SYMBOL (SN)	NOT NECESSARY	574.20	-
1	COVER, ENGINE UNDER (SN)	NOT NECESSARY	218.30	-
1	GUARD, FR BUMPER (SN)	NOT NECESSARY	644.30	-
			7,203.90	2,357.40
	<b><u>LABOUR</u></b>			
	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER AND FRONT SUPPORT.		1,440.00	960.00

Report Ref No. CS/LAW23001806/Rvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT ON FRONT BUMPER AND FRONT SUPPORT.		1,632.00	816.00
	TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER.		240.00	240.00
	TO RESET ECU AND REPROGRAMME.		240.00	240.00
	SUPPLY FRONT NO PLATE AND CASING.		96.00	96.00
	TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR ETC TO ENABLE REPAIR.	NOT NECESSARY	960.00	-
			4,608.00	2,352.00
<b>GRAND TOTAL</b>			<b>11,811.90</b>	<b>4,709.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,709.40</b>

Report Ref No. CS/LAW23001806/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.