



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HOLMAN FENWICK WILLAN SINGAPORE LLP 30 RAFFLES PLACE, #24-01, OXLEY @ RAFFLES, SINGAPORE 048622			Ref: CS/LAW23001806/Rvy3e2 Date: 14/03/2023 Code: L181	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PALLET DOLLY	Veh. Inspected	SMN 9129B	
Policy No.		Coverage (\$)	0.00	
Claim No.	67925-325	Excess (\$)	0.00	
Assign From	DARRYL ANDREW QUEK	Assign Date	06/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS RX270A	c.c	2672	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTJZA11AX02477361	Colour	WHITE	
Odometer	124174 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	TOURADOR	6 mm	
L/H Front Tyre	235/60 R18	TOURADOR	6 mm	
R/H Rear Tyre	235/60 R18	TOURADOR	6 mm	
L/H Rear Tyre	235/60 R18	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/01/2023	Inspection Date	17/02/2023	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	