



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/HSB23001807/Kqp3e2 Date: 01/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2469H	Veh. Inspected	GBF 7972T
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04JIL	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	17/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDH2015022100	Colour	WHITE
Odometer	113933 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	FALKEN	9 mm
L/H Front Tyre	195 R15X8	FALKEN	9 mm
R/H Rear Tyre	195 R15X8	YOKOHAMA	7 mm
L/H Rear Tyre	195 R15X8	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/02/2023	Inspection Date	20/02/2023
Survey held at	BLK 5038 ANG MO KIO IND PARK 2 #01-405 SINGAPORE		
Repairer	MASSIVE TRADING & AUTO		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	