Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541 H/p 91082728

Lim Ah Song Trading Blk 644 Ang Mo Kio Ave 4 #11-860 Singapore 560644

Vehicle No : GBF 7972 T

Make/Model: Toyota Hiace

Year : 2016

Not Nothank (/Ry & Rearry After Rains 4. Say,

83718.75

Qty	Description	Unit Price Amount
Estimate	Cost Of Repair	
1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc 1 pc	Rear tail-gate assy Rear tail-gate windscreen moulding Rear tail-gate emblem " Logo " Rear end panel Rear bumper Rear bumper inner step panel Rear o/s bumper side retainer Rear boot rubber Rear o/s tail-lamp Rear o/s tail-lamp apron panel Rear exhaust silencer	\$1,850.70 \$ \$75.20 \$ \$65.70 \$ \$487.60 \$ \$576.20 \$ \$387.50 \$ \$387.50 \$ \$75.60 \$ \$205.70 \$ \$465.80 \$ \$1,55.70 \$ \$750.80 \$ \$5,096.50 \$ \$1,274.13 \$ \$3,822.37
1 pc 1 pc 1 pc 1 pc 1 pc	Rear windscreen sealant Rear tail-gate sticker " 70 kmph " Rear tail-gate sticker " 8 PAX " Rear reverse sensor	New \$35.00 New \$15.00 New \$15.00 \$200.00

Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

To putty and spray paint

Check & reconnect wiring.

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

balance c/f

GBF 7972 T

balance b/f \$5,917.37

Labour Charges

Remove/refit rear windscreen glass to facilitate repair

\$120.00

Remove/refit rear tail-gate mechanism, inner trim to new door.

\$100.00 606

Remove/renew rear exhaust silencer

\$6,287.37

Total