



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL
C/O MCLARENS SINGAPORE PTE LTD
61 ROBINSON ROAD
#09-01, 61 ROBINSON SINGAPORE 068893

Ref: CS/MCS23001814/Tqy3e2

Date: 10/07/2023

Code: III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLT 7956Z
Policy No.		Coverage (\$)	0.00
Claim No.	SIN.228603	Excess (\$)	0.00
Assign From	ERNEST KHONG	Assign Date	16/02/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLC250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDC2533462F313141	Colour	BLACK
Odometer	139629 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R19	MICHELIN	6 mm
L/H Front Tyre	235/55 R19	MICHELIN	6 mm
R/H Rear Tyre	235/55 R19	MICHELIN	6 mm
L/H Rear Tyre	235/55 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/02/2023	Inspection Date	21/02/2023
Survey held at	143 BUKIT TIMAH ROAD S 229843		
Repairer	BOSS GARAGE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------