



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL C/O MCLARENS SINGAPORE PTE LTD 61 ROBINSON ROAD #09-01, 61 ROBINSONSINGAPORE 068893			Ref: CS/MCS23001815/Svy3e2 Date: 03/05/2023 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKA 2669Y	
Policy No.	SIN.228620	Coverage (\$)	0.00	
Claim No.	LPL2023D0000521	Excess (\$)	0.00	
Assign From	ERNEST KHONG	Assign Date	17/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS ES300H	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTHB21B1902046797	Colour	GREY	
Odometer	91167 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R18	PIRELLI	6 mm	
L/H Front Tyre	235/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/45 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/01/2023	Inspection Date	21/02/2023	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	