

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-09, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : SKA 2669Y
Made : Toyota
Model : Lexus ES300H
Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bonnet X	1	\$ 1,838.40	\$ 1,838.40
2	Front Bonnet Hinge RH X	1	\$ 101.20	\$ 101.20
3	Front Bonnet Hinge LH X	1	\$ 101.20	\$ 101.20
4	Front Bonnet Lock X	1	\$ 170.10	\$ 170.10
5	Front Bumper CUF	1	\$ 1,251.50	\$ 1,251.50
6	Front Bumper Number Plate Garnish X	1	\$ 141.60	\$ 141.60
7	Front Bumper Side Retainer RH X	1	\$ 125.40	\$ 125.40
8	Front Bumper Side Retainer LH X	1	\$ 125.40	\$ 125.40
9	Front Bumper Inner Sponge CUF	1	\$ 205.90	\$ 205.90
10	Front Bumper Reinforcement X	1	\$ 1,091.10	\$ 1,091.10
11	Front Bumper Headlamp Washer Cover RH X	1	\$ 134.20	\$ 134.20
12	Front Bumper Headlamp Washer Cover LH miss	1	\$ 134.20	\$ 134.20
13	Front Bumper Headlamp Washer Bracket RH X	1	\$ 33.80	\$ 33.80
14	Front Bumper Headlamp Washer Bracket LH X	1	\$ 33.80	\$ 33.80
15	Front Bumper Headlamp Washer Jet RH X	1	\$ 686.80	\$ 686.80
16	Front Bumper Headlamp Washer Jet LH Br	1	\$ 686.80	\$ 686.80
17	Front Bumper Fog Lamp Garnish RH X	1	\$ 174.30	\$ 174.30
18	Front Bumper Fog Lamp Garnish LH CUF	1	\$ 174.30	\$ 174.30
19	Front Bumper Bracket RH X	1	\$ 161.10	\$ 161.10
20	Front Bumper Bracket LH X	1	\$ 161.10	\$ 161.10
21	Front Bumper Distance Sensor RH X	1	\$ 490.80	\$ 490.80
22	Front Bumper Distance Sensor LH Faulty	1	\$ 490.80	\$ 490.80
23	Front Bumper Distance Sensor Retainer RH X	1	\$ 19.20	\$ 19.20
24	Front Bumper Distance Sensor Retainer LH X	1	\$ 19.20	\$ 19.20
25	Front Grille Assembly CUF	1	\$ 2,000.30	\$ 2,000.30
26	Front Grille Emblem X	1	\$ 477.90	\$ 477.90
27	Front Radiator Grille Moulding X	1	\$ 976.70	\$ 976.70
28	Front Radiator Grille Moulding X	1	\$ 594.20	\$ 594.20
29	Front Headlamp Assembly RH X	1	\$ 12,326.20	\$ 12,326.20
30	Front Headlamp Assembly LH Br	1	\$ 12,326.20	\$ 12,326.20
31	Front Support Panel X	1	\$ 2,124.00	\$ 2,124.00
32	Front Support Panel Top Garnish X	1	\$ 427.50	\$ 427.50
33	Aircon Condenser X	1	\$ 2,726.00	\$ 2,726.00

\$1035.20

\$70

\$151.30

\$170.70

\$361

34	Radiator	X	1	\$ 3,148.80	\$ 3,148.80
35	Front Fender RH	X	1	\$ 1,941.10	\$ 1,941.10
36	Front Fender LH	X	1	\$ 1,941.10	\$ 1,941.10
37	Front Fender Inner Shield RH	X	1	\$ 502.60	\$ 502.60
38	Front Fender Inner Shield LH	X	1	\$ 502.60	\$ 502.60
				Parts Sub Total :	\$ 50,547.40
				Discount 10%	\$ 5,054.74
				PARTS TOTAL :	\$ 45,492.66

T = 10986.20
10% = 1098.62

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate X	1	\$ 50.00	\$ 50.00
2	Front Bumper Clips - Set X	1	\$ 50.00	\$ 50.00
3	Front Grille Assembly Clips - Set X	1	\$ 50.00	\$ 50.00
4	Front Headlamp Clips - Set X	1	\$ 50.00	\$ 50.00
5	Front Support Panel Top Garnish Clips - Set X	1	\$ 30.00	\$ 30.00
6	Front Fender Inner Shield Clips - Set X	1	\$ 80.00	\$ 80.00
7	Radiator Coolant X	1	\$ 60.00	\$ 60.00
8	Front Bonnet Sealant X	1	\$ 150.00	\$ 150.00
9	Front Support Panel Sealant X	1	\$ 150.00	\$ 150.00
10	Front Fender RH Sealant X	1	\$ 150.00	\$ 150.00
11	Front Fender LH Sealant X	1	\$ 150.00	\$ 150.00
SPECIAL NETT TOTAL :				\$ 970.00

✓ REC

50

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 1,800.00
2	To Spray Paint Affected Areas	\$ 1,800.00
3	Wiring & Bulb Check	\$ 100.00
4	To Remove & Refix Aircon Condenser and Top Up Gas	\$ 150.00
5	To Remove & Refix Radiator and Pressure Test	\$ 150.00
6	To Remove & Refix Front Bumper Distance Sensor	\$ 120.00
7	To apply anti rust on affected parts	\$ 120.00
8	To Conduct Water Leak Test	\$ 100.00
9	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00
		LABOUR TOTAL : \$ 4,820.00

200
200
30
X MV
30
X
X NV

4 days

L/S

21/2/23

5 30pm

T = 10398.21

W/S = 2079.64

= 8318.56

~8300x

PARTS TOTAL : \$ 45,492.66

SPECIAL NETT TOTAL : \$ 970.00

LABOUR TOTAL : \$ 4,820.00

GRAND TOTAL : \$ 51,282.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: