



Your Ref: S2M048ML

Date: 30th March 2023

Our Ref: CS3/ASM22007646/Sqp3m4-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard
#48-01 Marina Bay Financial Centre Tower 2
Singapore 018983
(The Motor Claims Department)

Attn: Khor Saw Theng

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMZ 3505A
INSURED VEHICLE: SMV 5534Z
ACCIDENT DATE: 08/08/2022**

We thank you for your instruction on 16/02/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMZ 3505A from Automax Survey.
- b) Singapore Accident Statement of Vehicles SMZ 3505A and SMV 5534Z.
- c) Police Report of Vehicle SMZ 3505A.
- d) Final Repair Bill of SMZ 3505A from M/s Hup Ley Huat Motor Spray Painting Services.
- e) Colour damaged vehicle photographs of SMZ 3505A.

Pre-Repair Inspection Date: 12/08/2022 at M/s Hup Ley Huat Motor Spray Painting Services, Blk 1 Kaki Bukit Ave 6 #01-35 Autobay, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMZ 3505A
Make & Model	: Toyota Camry Hybrid 2.5 Ascent Sports Cvt
Year of Registration	: 2021
Chassis Number	: JTNB23HK603078190
Engine Capacity	: 2487 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.