

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 03.02.2023

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : GBL5003Y
MODEL : NISSAN NV350
DATE OF ACCIDENT : 02.02.2023
TIME OF ACCIDENT : 14:10 HOURS

Xiao Tang

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 688.70	\$ 688.70
2	REAR BUMPER STEP PANEL <i>Dented</i>	1	\$ 269.60	\$ 269.60
3	REAR BUMPER SIDE HOLDER CLIP <i>New</i>	6	\$ 7.50	\$ 45.00 <i>30</i>
4	TAIL GATE <i>Dented</i>	1	\$ 1,816.70	\$ 1,816.70
5	TAIL GATE CATCH <i>For</i>	1	\$ 31.80	\$ 31.80
6	TAIL GATE SIDE STOPPER <i>For</i>	2	\$ 19.00	\$ 38.00
7	TAILGATE LOGO <i>new</i>	1	\$ 175.40	\$ 175.40
8	TAIL GATE OUTER MOULDING <i>Not new</i>	1	\$ 463.90	\$ 463.90
9	TAIL GATE EMBLEM 'NV350' <i>For new</i>	1	\$ 89.70	\$ 89.70
10	TAIL GATE EMBLEM 'CARAVAN'	1	\$ 98.60	\$ 98.60
11	TAIL GATE WEATHER STRIP <i>lit</i>	1	\$ 175.30	\$ 175.30
12	TAIL GATE WEATHER STRIP PROTECTOR <i>Dented</i>	1	\$ 192.30	\$ 192.30
13	TAIL GATE INNER LOCK <i>Dented</i>	1	\$ 394.10	\$ 394.10
14	TAIL LAMP <i>LH cracked</i>	2	\$ 225.40	\$ 450.80 <i>225.40</i>
15	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 461.60	\$ 461.60
16	REAR END PANEL (INNER) <i>Repair</i>	1	\$ 986.70	\$ 986.70
17	REAR FLOOR PANEL <i>Repair</i>	1	\$ 1,883.20	\$ 1,883.20
18	REAR FLOOR MAT <i>Not new</i>	1	\$ 981.60	\$ 981.60

4617.4
4155.66

TOTAL PRICE \$ 9,243.00
LESS 10% \$ 924.30
SUB TOTAL PRICE \$ 8,318.70

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL5003Y
 MODEL : NISSAN NV350
 DATE OF ACCIDENT : 02.02.2023
 TIME OF ACCIDENT : 14:10 HOURS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
3	TAIL GATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>+</i>
4	TAIL GATE STICKER "70KM/H" <i>3 per</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
5	TAIL GATE STICKER "8PAX"	1	\$ 40.00	\$ 40.00 <i>15</i>
6	TAIL GATE WINDSCREEN SEALANT <i>3 per</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
7	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00 <i>30</i>
8	TAIL GATE CHINESE WORK STICKER <i>new</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
9	TAILGATE STICKER 'ZY' <i>new</i>	1	\$ 60.00	\$ 60.00 <i>20</i>
10	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00 <i>10</i>
11	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
12	REVERSE SENSOR <i>2 per</i>	1	\$ 220.00	\$ 220.00 <i>200</i>

460

TOTAL \$ 890.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>1000</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>900</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>60</i>
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>X</i>
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	<i>50</i>

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL5003Y
 MODEL : NISSAN NV350
 DATE OF ACCIDENT : 02.02.2023
 TIME OF ACCIDENT : 14:10 HOURS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

2190

TOTAL \$ 4,190.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,208.70
 TOTAL LABOUR COST : \$ 4,190.00
 TOTAL REPAIR COST : \$ 13,398.70

Adrian Li
L/S 03/02/23.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 6805.66
L/S: 5.41K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: