

✓

Kenneth

ASSIGNMENT

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9345E

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

14 FEB 2023

PART

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 WEATHERSTRIP, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 REAR TAILGATE TOYOTA LOGO
- 1 REAR TAILGATE WORDING 'PRIUS'
- 1 REAR TAILGATE WORDING 'HYBRID'

SHD9345E

JTDKB3FUX03079805

200303878K

TOYOTA

PRIUS

12/02/2023

SNA4122J/CHINA

17/05/2019

LIST

\$	Bu	558.39	—
\$	Bu/M	726.92	—
\$	M	19.43	—
\$	Sm	155.72	X
\$	M/Sm	155.72	—
\$	By	419.90	2
\$	Sm	147.11	X
\$	Sm	148.58	X
\$	Sm	220.50	X
\$	Sm	304.92	X
\$	CM	290.43	X
\$	Sm	159.39	X
\$	R	824.46	X
\$	R	1,099.46	X
\$	R	1,443.86	X
\$	Sm	469.25	X
\$	M/Sm	1,171.38	—
\$	Sm	305.66	X
\$	Sm	305.66	X
\$	R	77.18	X
\$	R	77.18	X
\$	M	90.30	—
\$	M	68.88	—
\$	M	68.88	—
TOTAL	\$	9,309.09	
25%	\$	1,666.03	
	\$	4,998.08	

Special Nett

- 1 PARKING AID
- 1 REAR LOWER BUMPER CLIP

\$	CM	700.00	25CM—
\$	M	65.00	6CM—

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2302-063**SHD9345E**

1	REAR BUMPER CLIP	\$	na	60.00	✓
2	WINDSCREEN SEALANT	\$	na	150.00	80.00
1	WINDSCREEN MOULDING	\$	na	200.00	✓
1	WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	30.00
1	REAR TAILGATE STICKER "Trans-Cab"	\$	na	80.00	30.00
1	REAR TAILGATE STICKER "6555-3333"	\$	na	80.00	30.00
1	REAR BUMPER PROTECTOR	\$	na	180.00	X
1	REAR NUMBER PLATE WITH HOLDER	\$	na	140.00	X

TOTAL**\$ 1,785.00****TOTAL PARTS \$ 6,783.08****LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 500

To transfer of Fender fittings, attachments and perform water seepage test.

\$ na 480.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 660

To reinstall rear bumper parking sensor.

\$ 170.00 300

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ na 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ na 380.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ na 240.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2302-063**SHD9345E**

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ ~ ~ 380.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 201

TOTAL \$ 5,760.00**Over All Total \$ 12,543.08****(PART-BY-PART) Repair Days**

.05 days

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: