



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CS3/CTI22000795/Rvy3e2-1 Date: 11/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	PA 8801H	Veh. Inspected	PC 5108K
Policy No.	DMB1SNA00016692101	Coverage (\$)	0.00
Claim No.	SNM22D200494/C02	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	26/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COASTER 23 SEATER ABS	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTGEP538706001355	Colour	WHITE
Odometer	360423 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/75 R17.5	LING LONG	7 mm
L/H Front Tyre	215/75 R17.5	LING LONG	7 mm
R/H Rear Tyre	215/75 R17.5 (D)	LING LONG	7/7 mm
L/H Rear Tyre	215/75 R17.5 (D)	LING LONG	7/7 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	18/01/2022	Inspection Date	27/10/2022
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	