



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile **CS3/CTI22000795/Rvy3-1**

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Ref: ~~CS3/CTI22000795/Rvy3-1~~

Date: ~~24/01/2022~~ 26/10/2022

Code: CTI

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	PA 8801H	<b>Veh. Inspected</b>	PC 5108K
<b>Policy No.</b>	DMB1SNA00016692101	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SNM22D200494/C02/IRENE	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IRENE TAY	<b>Assign Date</b>	<del>24/01/2022</del> 26/10/2022

## 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

## 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

## 4. Description of Damages

--

## 5. General Information

<b>Accident Date</b>	18/01/2022	<b>Inspection Date</b>	24/01/2022
<b>Survey held at</b>	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.