

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06761

Vehicle Insured : SFA1415D
Accident Date : 14-Feb-2023

Date : 15-Feb-2023

Our Ref : 023034 (AIG) / CHAN

PAGE : 1

KOH MENG HENG
BLK 180 ANG MO KIO AVE 5
#07-2952
Singapore 560180

Not Authorised
L1 Rep &
Recovery After Paint

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER ELEGANCE SCZ36A

1 pc Tail gate		<i>Pr</i> 2,378.00 ✓
1 pc Tail gate lower moulding		<i>na</i> 51.90 —
2 pcs Tail gate side moulding	@ S\$ 26.20	<i>na</i> 52.40 —
1 pc Tail gate "HARRIER" EMBLEM		<i>na</i> 73.70 —
1 pc Rear bumper fascia		<i>Buc/na</i> 1,571.30 ✓
1 pc Rear bumper lower spoiler		<i>Red/na</i> 457.30 ✓
2 pcs Rear bumper reflector	@ S\$ 65.50	<i>na</i> 131.00 X
1 pc Rear bumper sponge		121.60 ?
1 pc Rear end panel		885.60 ?
1 pc Rear end panel top garnish		438.30 ?

6,161.10

Less 25% : 1,540.28

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip (set)
- 1 pc Rear bumper reverse sensor

na 4,620.82 *Paint*
na 60.00 sn
na 40.00 sn ✓
300.00 sn ?

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and rear seats, trim board and carpet

120.00 ?

To apply undersealing

60.00 *301*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SFA1415D

To putty and spray replaced parts

600.
700.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.
600.00

Total : S\$ 6,650.82

Singapore Dollars Six Thousand Six Hundred and
Fifty and Cents Eighty Two Only