

ASS. REC. BY:

REF:

A/G 1 23 0018331/Ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SC 836A

Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Harrie

c.c

1986

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

84 744

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

ZSU 60 0086405

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

225/85R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

6 mm

R/Bal. _____

4 mm

L/Bal. _____

6 mm

L/Bal. _____

4 mm

D.O.A. _____

14/2/23

D.O.I. _____

16/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/6 11.20 @ 3800 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee: _____

Transportation

Add Fee: _____

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

S + RS. \$

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06761

Vehicle Insured : SFA1415D
Accident Date : 14-Feb-2023

Date : 15-Feb-2023

Our Ref : 023034 (AIG) / CHAN

PAGE : 1

KOH MENG HENG
BLK 180 ANG MO KIO AVE 5
#07-2952
Singapore 560180

Not Notified
L1 Rep \$3800
Recovery After Paim

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER ELEGANCE SCZ36A

- 1 pc Tail gate
- 1 pc Tail gate lower moulding
- 2 pcs Tail gate side moulding
- 1 pc Tail gate "HARRIER" EMBLEM
- 1 pc Rear bumper fascia
- 1 pc Rear bumper lower spoiler
- 2 pcs Rear bumper reflector
- 1 pc Rear bumper sponge
- 1 pc Rear end panel
- 1 pc Rear end panel top garnish

	<i>By</i>	2,378.00	✓
	<i>mc</i>	51.90	—
@ S\$ 26.20	<i>mc</i>	52.40	—
	<i>mc</i>	73.70	—
	<i>Buclaw</i>	1,571.30	✓
	<i>Pullan</i>	457.30	✓
@ S\$ 65.50	<i>mc</i>	131.00	✓
	<i>CM</i>	121.60	✓
	<i>R</i>	885.60	✓
	<i>Pr</i>	438.30	✓
		6,161.10	
Less 25% :		1,540.28	

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip (set)
- 1 pc Rear bumper reverse sensor

To remove & refix rear windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To apply undersealing

4708.20
1126.55
3529.65
4,620.82 *4000*
mc 60.00 *sn*
mc 40.00 *sn*
Short 200 300.00 *sn*
150.00 *1201*
60 120.00 *601*
60.00 *301*

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SFA1415D

Page : 2

To putty and spray replaced parts

650/-
700.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

550/-
600.00

Total : S\$ 6,650.82

Singapore Dollars Six Thousand Six Hundred and
Fifty and Cents Eighty Two Only

L/CUM
3800
@
5 days

P3529.65
SN 280.00
L 1310.00

5119.65
1279.91

3839.73

→
Kenneth Pte Cothran
7/11/11

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06761

Vehicle Insured : SFA1415D
Accident Date : 14-Feb-2023

Date : 15-Feb-2023

Our Ref : 023034 (AIG) / CHAN

PAGE : 1

KOH MENG HENG
BLK 180 ANG MO KIO AVE 5
#07-2952
Singapore 560180

Not Notified
L1 Rep &
Resurvey After Painting

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER ELEGANCE SCZ36A

1 pc	Tail gate		<i>At</i> 2,378.00	✓
1 pc	Tail gate lower moulding		<i>na</i> 51.90	—
2 pcs	Tail gate side moulding	@ S\$ 26.20	<i>na</i> 52.40	—
1 pc	Tail gate "HARRIER" EMBLEM		<i>na</i> 73.70	—
1 pc	Rear bumper fascia		<i>Bucl/na</i> 1,571.30	✓
1 pc	Rear bumper lower spoiler		<i>pd/na</i> 457.30	✓
2 pcs	Rear bumper reflector	@ S\$ 65.50	<i>na</i> 131.00	X
1 pc	Rear bumper sponge		121.60	?
1 pc	Rear end panel		885.60	?
1 pc	Rear end panel top garnish		438.30	?

			6,161.10	
			Less 25% :	1,540.28

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper clip (set)
- 1 pc Rear bumper reverse sensor

na 4,620.82 *80/na*
na 60.00 sn
na 40.00 sn ✓
300.00 sn ?

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *120/*

To remove roof lining, front and rear seats, trim board and carpet

120.00 ?

To apply undersealing

60.00 *30/*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SFA1415D

Page : 2

To putty and spray replaced parts

600.
700.00

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.
600.00

Total : S\$ 6,650.82

Singapore Dollars Six Thousand Six Hundred and
Fifty and Cents Eighty Two Only

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	111F
Vehicle Details	
Vehicle No.:	SCZ36A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Feb 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	3ZRB688554
Chassis No.:	ZSU600066405
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$27,211.00
Original Registration Date:	04 Mar 2016
First Registration Date:	04 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$25,096.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Mar 2026
PARF Rebate Amount:	\$16,312.00
Intended COE Rebate Details	
COE Expiry Date:	03 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$17,502.00
Total Rebate Amount:	\$33,814.00

The information contained herein is correct as at 16 Feb 2023

OK