

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23001834/UPA3Q2**Date:** 15/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220022091
Claimant Vehicle No :	FBN1629H	Insured Vehicle No :	SNE9901Z
Date of Loss:	31/01/2023	Nature of Claim:	TP
		Claim No:	8571964929SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1629H	Engine No:	G3H6E0009672
Make & Model:	YAMAHA NMAX155, 155cc ABS	Chassis No:	MH3SG431000007457
Reg. Date:	27/07/2018 (Man. Year: 2018)	Odometer:	79187 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110-70-13	Rear Tyre Size:	130-70-13
Front Left Side:	Timsun 6 mm	Rear Left Side:	Timsun 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	450.50	274.10	176.40	39.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	475.00	395.00	80.00	16.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	925.50	669.10	256.40	27.70
Approved Total (Overridden) (\$\$)		530.00		
(\$\$)	925.50	530.00	395.50	42.73
+ GST 8.00/8.00% (\$\$)	74.04	42.40	31.64	42.73
Nett Amount (\$\$)	999.54	572.40	427.14	42.73
+ Loss of Use (3.0 x S\$20.00/day) (\$\$)		60.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		634.40		

INSPECTION

Date of Assignment:	20/02/2023	Ban Hock Hin Co. Pte Ltd (HQ)
Date Inspected:	20/02/2023 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	3.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BALANCER HANDLE	Not Necessary	16.00 F	*- FL
2	1		*BELLY PAN	Cut	23.00 F	*23.00 FL
3	1		*BOARD FOOTREST RH	Cut	36.00 F	*36.00 FL
4	1		*COVER CLUTCH OUTER DAMPER 3	Not Necessary	5.00 F	*- FL
5	1		*COVER RADIATOR	Not Necessary	15.00 F	*- FL
6	1		*COVER SIDE LOWER RH (WHITE)	Cut	15.00 F	*15.00 FL
7	1		*COVER SIDE REAR RH (WHITE)	Cut	20.00 F	*20.00 FL
8	1		*COWLING FRONT RH (WHITE)	Cut	22.00 F	*22.00 FL
9	1		*EMBLEM (YAMAHA) LOGO	Necessary	10.00 F	*10.00 FL
10	1		*FORK FRONT ASSY RH	Not Necessary	120.00 F	*- FL
11	1		*LEVER BRAKE RH	Scratched	12.00 F	*12.00 FL
12	1		*MIRROR RH	Cut	25.00 F	*25.00 FL
13	1		*PANEL 2 (GREY) RH	Cut	15.00 F	*15.00 FL
14	1		*PROTECTOR EXHAUST	Cut	26.00 F	*26.00 FL
15	2		*STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH	Necessary	30.00 FS	*30.00 FS
16	1		*STICKER (CISCO) COWLING FRONT RH	Necessary	25.00 FS	*25.00 FS
17	1		*STICKER (CISCO) LINING COVER REAR RH	Necessary	10.50 FS	*10.50 FS
18	1		*STICKER (CISCO) MUDGUARD FRONT	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	450.50	294.50
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	20.40
Total Parts (\$\$)	450.50	274.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY LACQUER ON MUDGUARD FRONT	New	35.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	330.00	250.00
3	SPRAY LACQUER ON COWLING FRONT RH	New	65.00	65.00
4	SPRAY LACQUER ON REAR SIDE COVER RH	New	45.00	45.00
Gross Labour Cost (\$)			475.00	395.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >