

(05/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG 23001834/Upa3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐ : Preli. Report☐ : Final Report

Add Fee:

Days Of Repair:

Resurvey No. of Trip:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:


Transportation:

) S + RS. SI


) Photos

) Others

TOTAL



21/3/23  
No 2018 model from Sabik Mart  
have video n/s body n/c  
1/5 & 530 informed Raymond





**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES



Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD  
CHARTIS BUILDING  
78 SHENTON WAY  
#07-16  
SINGAPORE 079120

ATTN: 64193000

TEL :  
FAX :

VEHICLE NO. : FBN1629H MILEAGE: 79187  
MAKE/MODEL : YAM - YAMAHA NMAX155 ABS

*not Authored  
20/2/23  
1/5 & 530  
3 days  
whisper after 1 day*

## QUOTATION

NO. : 42916 - Rev. 1

Supplementary 1 To QTN: 42682

DATE : 06/03/2023  
JOB NO. : LEJB20244259  
FROM : SHIWEI

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 55166 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	2.00	\$8.00	17 \$16.00 X
2	BELLY PAN P/N: 58094 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$23.00	CU7 \$23.00
3	BOARD FOOTREST RH P/N: 59589 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$36.00	CU7 \$36.00
4	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$5.00	17 \$5.00 X
5	COVER RADIATOR P/N: 63127 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$15.00	17 \$15.00 X
6	COVER SIDE LOWER RH (WHITE) P/N: 58117 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$15.00	CU7 \$15.00
7	COVER SIDE REAR RH (WHITE) P/N: 58102 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$20.00	CU7 \$20.00

*102*

*bizSAFE*



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg  
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383  
ISO 9001: 2015



S/N	Description	Action	Qty	Unit Price	Amount
8	COWLING FRONT RH (WHITE) P/N: 59594 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$22.00	cu7 \$22.00
9	EMBLEM (YAMAHA) LOGO P/N: 57069 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$10.00	ner \$10.00
10	FORK FRONT ASSY RH P/N: 60926 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$120.00	17 \$120.00
11	LEVER BRAKE RH P/N: 58185 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$12.00	scr \$12.00
12	MIRROR RH P/N: 58187 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$25.00	cu7 \$25.00
13	PANEL 2 (GREY) RH P/N: 58081 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$15.00	cu7 \$15.00
14	PROTECTOR EXHAUST P/N: 58086 Reason: CRACKED / BENT / BROKEN / DAMAGED- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$26.00	cu7 \$26.00
15	SPRAY LACQUER ON COWLING FRONT RH Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	Spray	✓ 1.00	\$65.00	\$65.00
16	SPRAY LACQUER ON REAR SIDE COVER RH Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	Spray	✓ 1.00	\$45.00	\$45.00
17	STICKER (CERTIS CISCO) LOGO NEW MODEL LH/RH P/N: 61181 - (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	✓ 1.00	\$30.00	ner \$30.00
18	STICKER (CISCO) COWLING FRONT RH P/N: 58617 Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	✓ 1.00	\$25.00	ner \$25.00
19	STICKER (CISCO) LINING COVER REAR RH P/N: 58613 Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	✓ 1.00	\$10.50	ner \$10.50

Labour

Labour

bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
20	STICKER (CISCO) MUDGUARD FRONT P/N: 58618 Reason: NECESSARY- (REPORTED BY MECHANIC) Stock Availability (Days): 1	REPLACE	1.00	\$25.00	\$25.00
21	SPRAY LACQUER ON MUDGUARD FRONT Reason: NECESSARY- (REPORTED BY MECHANIC)	Spray	1.00	\$35.00	\$35.00
22	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	6.00	\$55.00	\$330.00

SUB TOTAL \$925.50

GST @ 8 % \$74.04

**TOTAL (SGD) \$999.54****Remarks:**

Validity: 30 days

For &amp; on Behalf of

**BAN HOCK HIN CO PTE LTD****SHIWEI**

Acknowledge &amp; Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-204  
102  
p-183.60  
S.N 90.5  
395  
669.1

bizSAFE

