

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

Desktop Survey

Veron

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	WH1722
Policy No:	SP2003380431-01	Date of Loss:	17/02/2023
Vehicle Reg. No.:	SKL8820D => SKL 6541Y	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HOLGER HELMUTH LINDNER		
Make/Model:	MERCEDES-BENZ C180, 1.6 (A)	Vehicle Reg. Date:	02/01/2014
Vehicle Colour:	WHITE		
Engine No:	27491030064114	Chassis No:	WDD2043312G134038
Odometer:	57690 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7 4		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,772.80
Miscellaneous Items	85.00
Labour	1,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,517.80
+ GST 8.00% (S\$)	601.42
Nett Amount (S\$)	8,119.22

This claim is handled by: CHAN PEI PEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2023)

Parts: M1-COUPE MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SKL8820D/18/02/2023 10:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet	0.00	0.00	*1,302.00 F BT
2	1		*Bonnet logo badge	0.00	0.00	*48.00 F NEC
3	1		*Front fender LH	0.00	0.00	*582.00 F XR
4	1		*Front fender shield LH (Front portion)	0.00	0.00	*84.00 F DIS
5	1		*Front fender shield LH (Rear portion)	0.00	0.00	*90.00 F XNN
6	1		*Headlamp LH	0.00	0.00	*636.00 F BR
7	1		*Headlamp panel LH	0.00	0.00	*186.00 F ?
8	1		*Front bumper	0.00	0.00	*786.00 F BW
9	1		*Front bumper side retainer RH/LH@2*\$17	0.00	0.00	*34.00 F NEC
10	1		*Front bumper inner side bracket LH	0.00	0.00	*60.00 F ?
11	1		*Fog lamp LH	0.00	0.00	*342.00 F ?
12	1		*Fog lamp cover with outer chrome LH	0.00	0.00	*60.00 F CRA
13	1		*Front bumper lower side chrome LH	0.00	0.00	*60.00 F CUT
14	1		*Center grille with logo badge	0.00	0.00	*552.00 F XNN
15	1		*Front reinforcement	0.00	0.00	*234.00 F ?
16	1		*Front reinforcement side panel LH	0.00	0.00	*24.00 F ?
17	1		*Front bumper sponge	0.00	0.00	*84.00 F ?
18	1		*Radiator air guide RH/LH@2*\$42	0.00	0.00	*84.00 F ?

F=Franchise part.

Sub Total (\$\$)	5,248.00
+ Margin on L,N Items 10.00% (\$\$)	524.80
Total Parts (\$\$)	5,772.80

Wah Hong Motors & Credit Pte Ltd/SKL8820D/18/02/2023 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Center grille clips	25.00 X NH
2	1	Front bumper clips	35.00 NEC
3	1	Front fender shield clips LH	25.00 NEC
Sub Total (S\$)			85.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	600 800.00 ✓
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	500 800.00 ✓
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00 ✓
Gross Labour Cost (S\$)			1,660.00

Wah Hong Motors & Credit Pte Ltd/SKL8820D/18/02/2023 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- NOT AUTHORISE
- EXCESS \$1000
- P/P OR L/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: