



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 263L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	FRONT RH DOOR HINGE @\$128.00 (SN) (CONSISTENT)		256.00	-
			256.00	-
	<u>LABOUR</u>			
	TO PANEL BEATING ON THE RH FRONT DOOR, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR HINGE.		280.00	200.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON ACCIDENT DAMAGED AREA.		500.00	400.00
	TO REMOVE AND REFIT FOR THE RH DOOR COMPARTMENT FOR FACILITIES REPAIR.		150.00	60.00
			930.00	660.00
GRAND TOTAL			1,186.00	660.00
RECOMMENDED COST OF REPAIRS				660.00

Report Ref No. CS/HSB23001849/Kwp3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.