



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: LOW GARNET		Ref: CS/HSB23001849/Kwp3m4 Date: 25/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3286L	Veh. Inspected	CB 263L
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04JJ2	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	20/02/2023
2. Vehicle Particulars & Condition			
Make & Model	GOLDEN DRAGON XML 5036 (A)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	LL3AACJ20NA004031	Colour	WHITE
Odometer	7992 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/70R15	LING LONG	9 mm
L/H Front Tyre	195/70R15	LING LONG	9 mm
R/H Rear Tyre	195/70R15	LING LONG	9 mm
L/H Rear Tyre	195/70R15	LING LONG	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/02/2023	Inspection Date	21/02/2023
Survey held at	SERVE YOU MOTOR SERVICE BLK 5033 ANG MO KIO IND PK 2 #01-265 SINGAPORE 569536		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	