



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: HO WINNIE		Ref: CS/HSB23001850/Kqp3m4 Date: 22/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2965Y	Veh. Inspected	SCE 66Z
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S3M04J92	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	20/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PREVIA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTEGD54M607121390	Colour	METALLIC BLACK
Odometer	89550 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	7 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	7 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/02/2023	Inspection Date	21/02/2023
Survey held at	LOH HENG BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	