

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 28 February 2023

To : LKK

Attn : Ah Kit

Tel : 87005631

VEHICLE NO : FBM 4346J

Suzuki UH 200A

ACCIDENT DATE: 10 February 2023

Description	Qty	Quotation \$
1 Handle Bar	1	130.00 BT ✓
2 Head Lamp Assembly	1	450.00 SCR \$420
3 Front Visor	1	850.00 SCR \$370
4 Front V Panel	1	130.00 BRC
5 Front LH Signal	1	90.00 SCR ✓
6 Front Fender	1	150.00 SCR ✓
7 Front Side Panel LH	1	250.00 SCR ✓
8 Front Side Panel RH	1	250.00 SCR ✓
9 Front RH Signal	1	95.00 SCR \$90 ✓
10 Fork Tube	1 set	1,480.00 BT R
11 Fork Under Bracket	1	680.00 BT SVC
12 Compartment Panel	1	330.00 SCR ✓
13 Balancer	1 set	70.00 SCR \$55
14 Brake Lever	1	75.00 SCR \$65
15 Mirror LH	1	60.00 SCR ✓
16 Rear Tail Panel LH	1	190.00 SCR ✓
17 Rear Tail Panel RH	1	190.00 SCR ✓
18 Rear Pillion Grip RH	1	150.00 SCR \$136
19 Exhaust Guard	1	130.00 SCR \$120
20 Rear Step Panel - Pillion LH	1	160.00 SCR ✓
21 Lower Panel LH	1	160.00 SCR ✓

22. shield leg lower - SCR \$128 Sub-Total

6,070.00 3847

Less 10%

607.00 384.7

23. front LH signal - SCR Sub-Total

5,463.00 3462.3

24. cut cover SCR \$245

24. shield leg side LH DRC \$128

VEHICLE NO : FBM 4346J

Suzuki UH 200A


Nett items

1	Rear Carner box - Kappa	380.00	SCR \$270
2	Towing fees	40.00	\$30
3	Remove & replace necessary parts, align & etc	350.00	✓
4	Remove & replace fork tube/bracket & top up fork oil	180.00	60 \$30
5	"200" sticker	95.00	60
6	Re-wrap seat cover	120.00	60
7	Burgman emblem x 2	250.00	120
8	Putty & respray paint	450.00	200

Sub-Total	1,865.00	\$120
Nett Total	7,328.00	\$4582.3

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you


SG 98 MOTOR PTE LTD

04 days

Lam Sum

Akid 0210312023