

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW
 #14-01 ASIA SQUARE TOWER 2
 SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0223-7255

Claim Type: Third Party

Accident Date: 08/02/2023

TP Veh Reg No: XE 7083 D

Estimate No: EST1509312

Date: 09 Feb 2023

Policy No: PNPV2019-0004023

Veh Reg No: SGK7775K

Make/Model: TOYOTA CAMRY 2.0
 AUTO ABS AIRBAG

Chassis No: MR053BK4107060804

Engine No: 1AZE178907

Reg. Date: 02/09/2010

Estimate Repair Cost to Vehicle No :SGK7775K

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	935.2000	1 PC	935.20	
2 REAR BUMPER SIDE HOLDER - LH/RH	83.9000	2 PC	167.80	
3 REAR BUMPER CLIPS	5.5000	10 PC	55.00	
4 REAR DOOR - RH	1,859.700	1 PC	1,859.70	
5 REAR DOOR OUTER HANDLE - RH	272.7000	1 PC	272.70	
6 REAR DOOR RUBBER - RH	272.7000	1 PC	272.70	
7 REAR TAILLAMP - RH	480.5000	1 PC	480.50	
8 FRONT DOOR - RH	2,142.700	1 PC	2,142.70	
9 FRONT DOOR OUTER PROTECTOR WITH CHROME - RH	105.0000	1 PC	105.00	
10 FRONT DOOR OUTER HANDLE - RH	87.4000	1 PC	87.40	
11 FRONT DOOR RUBBER - RH	272.7000	1 PC	272.70	
12 FRONT DOOR STICKER - RH	48.7000	1 PC	48.70	
13 SIDE MIRROR OUTER COVER - RH	105.6000	1 PC	105.60	
14 SIDE MIRROR LAMP - RH	79.8000	1 PC	79.80	
15 SIDE MIRROR GLASS - RH	296.0000	1 PC	296.00	
16 SIDE MIRROR ARM WITH HOUSING, MOTOR - RH	1,675.700	1 PC	1,675.70	
17 FRONT FENDER VVTI WORDINGS - RH	79.7000	1 PC	79.70	
18 HEAD LAMP - RH	850.6000	1 PC	850.60	
19 FRONT BUMPER	780.6000	1 PC	780.60	
20 FRONT BUMPER SIDE HOLDER - LH/RH	79.5000	2 PC	159.00	
21 FRONT BUMPER CLIPS	5.5000	10 PC	55.00	
22 REAR DOOR OUTER PROTECTOR WITH CHROME - RH	105.0000	1 PC	105.00	
23 REAR DOOR STICKER - RH	40.6000	1 PC	40.60	
			10,927.70	
		Less 25%	2,731.93	8,195.78
Labour				
24 TO KNOCK OUT DENTS ON REAR FENDER, FRONT FENDER, , REMOVE, REPLACE ACCIDENT PARTS	1,000.000	1 JOB	1,000.00	
25 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,600.000	1 JOB	1,600.00	
26 TO CHECK WIRING	40.0000	1 JOB	40.00	
27 TO TRANSFER 2 DOOR & DOOR FITTINGS	160.0000	1 JOB	160.00	
28 TO TUFF-KOTE	90.0000	1 JOB	90.00	
29 TO 4 WHEEL ALIGNMENT	80.0000	1 JOB	80.00	
			2,970.00	2,970.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD
12 MARINA VIEW
#14-01 ASIA SQUARE TOWER 2
SINGAPORE 018961
TEL: 63958963
ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0223-7255
Claim Type: Third Party
Accident Date: 08/02/2023
TP Veh Reg No: XE 7083 D

Estimate No: EST1509312
Date: 09 Feb 2023
Policy No: PNPV2019-0004023
Veh Reg No: SGK7775K
Make/Model: TOYOTA CAMRY 2.0
AUTO ABS AIRBAG
Chassis No: MR053BK4107060804
Engine No: 1AZE178907
Reg. Date: 02/09/2010

Estimate Repair Cost to Vehicle No :SGK7775K

Description	U/Price	Quantity	Price	Amount
			SS	SS
			Total	SS 11,165.78
			Add GST @ 8%	893.26
			Total Amount Payable	SS 12,059.04

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FIFTY NINE AND CENTS FOUR ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE