

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

TP INSURER:
DANIEL POR JIA JUN**Allianz Insurance Singapore Pte. Ltd. (HQ)**

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	10/02/2023
Vehicle Reg. No.:	SKW1854U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	POR KHENG CHYE		
Make/Model:	HYUNDAI VELOSTER, 1.6 (A)	Vehicle Reg. Date:	21/10/2015
Vehicle Colour:	WHITE		
Engine No:	G4FGFU404242	Chassis No:	KMHTC61CMGU276419
Odometer:	110807 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 ✓		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

*NOT WITH OTHER
11 Days @
the roomy after being*

COST OF CLAIMS

	Amount
Parts	3,214.20
Miscellaneous Items	3,710.00
Labour	2,220.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,144.20
+ GST 8.00% (S\$)	731.54
Nett Amount (S\$)	9,875.74

This claim is handled by: GOH JACQUELINE

ence

Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2023)
 Parts: M1-COUPE HYUNDAI VELOSTER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKW1854U)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH DOOR	<i>B1/way</i> 0.00	0.00	*550.00 F ✓
2	1		*FRONT LH DOOR STICKER (TOP & SIDE)	<i>Na</i> 0.00	0.00	*31.00 F ✓
3	1		*REAR LH DOOR	<i>B1/way</i> 0.00	0.00	*550.00 F ✓
4	1		*REAR LH DOOR STICKER (TOP & SIDE)	<i>Na</i> 0.00	0.00	*31.00 F ✓
5	1		*REAR LH FENDER	<i>Na</i> 0.00	0.00	*900.00 F ✗
6	1		*REAR BUMPER	<i>Na</i> 0.00	0.00	*800.00 F ✗
7	1		*REAR BUMPER SIDE RETAINER LH	<i>Na</i> 0.00	0.00	*60.00 F ✗
Sub Total (S\$)						2,922.00
+ Margin on L,N Items 10.00% (S\$)						292.20
Total Parts (S\$)						3,214.20

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

Particulars		Amount
<u>Miscellaneous Items</u>		
1	FROINT DOOR INNER TRIM BOARD CLIPS LH	NA 50.00 X
2	LH SIDE SKIRT COVER	NA 300.00 X
3	RE-WRAP FRONT LH DOOR HANDLE & REAR LH DOOR HANDLE	NA 120.00 X
4	RE-WRAP LH SIDE SKIRT COVER	1501N 200.00 nec
5	REAR FENDER SHIELD CLIPS LH	NA 45.00 X
6	REAR BUMPER CLIPS	NA 45.00 X
7	REAR DOOR INNER TRIM BORAD CLIPS LH	NA 50.00 X
8	RIM	100 4001N 2,300.00
9	TYRE	PM 600.00 X
Sub Total (\$\$)		3,710.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	10001 1,200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	5501 800.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	201 100.00
4	TO APPLY ANTI RUST TREATMENT	New	601 120.00
Gross Labour Cost (\$\$)			2,220.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >