

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

11/02/2023

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SLG6222H

1pc rear bumper *494.50*
 1pc rear bumper RH side retainer
 1pc rear bumper RH side lower garinsh
 1pc rear bumper towing cover
 1pc rear RH fender
 1pc rear RH lower arm
 1pc rear RH kunckle arm
 1pc rear RH adsorber
 1pc rear RH wheel bearing

Not working
11/2/23 81800h
Pruning After Paint
4 days

Bu/Incl	\$	928.35	✓
1pc	\$	141.40	X
1pc	\$	281.50	✓
1pc	\$	61.00	X
1pc	\$	981.50	X
1pc	\$	381.50	X
1pc	\$	481.50	X
1pc	\$	280.50	X
1pc	\$	358.20	✓

less 25%


\$	3,895.45
\$	973.86
\$	2,921.59

1pc rear RH tyre half cap
 1pc rear RH tyre

s.nett	\$	180.00	✓
s.nett	\$	180.00	X

remove & refit rear RH undercarriage
 alignment
 spray painting
 labour charges
 Total

\$	380.00	<i>501</i>
\$	80.00	<i>601</i>
\$	1,000.00	<i>601</i>
\$	1,000.00	<i>501</i>
\$	5,741.59	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: