

Survey Report & Invoice of Vehicle GBC 3537J Ref: IVS23/0311

RS

Renee Sia (LKK Auto)

    

To: Seah, Andy <Seah.Andy@libertyinsurance.com.sg>

Fri 3/3/2023 3:42 PM

Cc: Work Shop Estimate (SG) <workshoestimate@libert... +3 others

 GIA RPT.pdf
2 MB

 LIP-LKKInvoice-AC2301286.pdf
64 KB

 LKKAdjustment.pdf
220 KB

 LKKInspection.pdf
10 KB

 LKKPhoto.pdf
179 KB

 Resurvey Photo-1.pdf
40 KB

 Resurvey Photo-2.pdf
50 KB

 7 attachments (2 MB)  Download all

Dear Andy,

Enclose Survey Report of GBC 3537J.

Thank you.

Best Regards,

Renee | Reports
LKK Auto Consultants Pte.Ltd.
Phone: 6256-3561 Ext.111 Email: report@lkkauto.com
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Friday, March 3, 2023 9:50 AM
To: Lim, Stewart <lim.stewart@libertyinsurance.com.sg>; Seah, Andy <Seah.Andy@libertyinsurance.com.sg>; SUR <sur@lkkauto.com>; Report <report@lkkauto.com>; 'Seah, Ted' <seah.ted@libertyinsurance.com.sg>
Cc: Work Shop Estimate (SG) <workshoestimate@libertyinsurance.com.sg>
Subject: RE: FSR for GBC3537J & SMD6016R - 03.02.23 Liberty Ref IVS23/0311

Dear Stewart,

Please be informed that we are in the midst of preparing report.

Dear Reports Team,