

MYCAR PARTNERS PTE LTD
Company Reg No. 20187350M
10 Ang Mo Kio Industrial Park 2A
#03-18 AMK Autopoint
Singapore 568047

Tel: 97898985 email address: fajaliza@mycar.com.sg

Not Notarized
Re survey B4 point

Kennerch (LKK)
96910663

2 days

2124.56

ESTIMATE

HONDA VEZEL

SNF394R

DATE OF ACCIDENT 16/02/2023

Date : 20/2/2023

| DESCRIPTION | QUANTITY | RATE | AMOUNT | REMARKS |
|---|----------|-----------------|-----------------|-------------------|
| PARTS (LIST ITEM) | | | | |
| Car Plate Garnish | 1 | Dd \$70.50 | \$70.50 | } 455n |
| Car Plate Holder | 1 | Dd \$59.20 | \$59.20 | |
| Rear Bumper 1230.50 | 1 | nd \$1,290.40 | \$1,290.40 | ✓ |
| Rear Bumper Skirt 825.20 | 1 | moment \$845.40 | \$845.40 | ✓ |
| Tailgate Outer Garnish | 1 | \$885.20 | ln \$885.20 | X |
| 208 | | | Parts subtotal | \$3,150.70 |
| LABOUR | | | | |
| To remove the affected parts & fittings to commence repairs, panel beat & reshape the affected area | 1 | \$600.00 | \$600.00 | 200d |
| Respray paint, putty on parts replaced & repaired area | 1 | \$600.00 | \$600.00 | 220d |
| To remove & refix wiring & check all electrical components at damaged area for proper functions | 1 | \$80.00 | \$80.00 | 15L |
| To provide anti-rust treatment on affected areas | 1 | \$150.00 | nn \$150.00 | X |
| | | | Labour subtotal | \$1,430.00 |
| | | | Subtotal | \$4,580.70 |
| | | | Total | \$4,580.70 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: