

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III23001892/ANY3E2**Date:** 30/03/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0002324
<b>Claimant Vehicle No :</b>	SLF2422D	<b>Insured Vehicle No :</b>	SMQ7590Z
Date of Loss:	29/10/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0008010

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLF2422D</b>	Engine No:	3ZRB790059
Make & Model:	TOYOTA VOXY, 2.0(A)	Chassis No:	ZRR800207110
Reg. Date:	18/08/2016 (Man. Year: 2016)	Odometer:	84972 km
Colour:	Blue		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>1,500.00</b>	<b>-1,500.00</b>	

**INSPECTION**

Date of Assignment:	20/02/2023	
Date Inspected:	27/02/2023	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	M1-MPV	TOYOTA VOXY 2.0(A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF2422D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >