

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SLF2422D
VEHICLE MODEL : TOYOTA VOXY
CHASSIS NO : ZRR800207110

7P111
Hui Rong

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Deband</i>	1	\$ 1,080.40	\$ 1,080.40
2	REAR BUMPER SIDE HOLDER LH <i>2nd</i>	1	\$ 98.50	\$ 98.50
3	REAR BUMPER REFLECTOR LH <i>new</i>	1	\$ 89.80	\$ 89.80
4	REAR BUMPER TOW COVER <i>new</i>	1	\$ 38.90	\$ 38.90
5	TAILLAMP LOWER APRON <i>new</i>	1	\$ 385.10	\$ 385.10

TOTAL PRICE: \$ 1,692.70
LESS 25% \$ 423.17
SUB TOTAL PRICE: \$ 1,269.53

1564
1173

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	TAILLAMP LOWER APRON CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00

TOTAL : \$ 350.00

50

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 400.00	<i>300</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	<i>300</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>+</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	

TOTAL: \$ 1,300.00

680

ESTIMATE REPORT

TOTAL PARTS COST: \$ 1,619.53
TOTAL LABOUR COST: \$ 1,300.00
TOTAL REPAIR COST: \$ 2,919.53

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

Total: 1903

L/S: 1.5K

03 Days

1.5K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: