Estimate

				L	stimate						
LKK AUTO CONSULTANTS PTE LTD						orma I	nvoice N	o:	Date: Mar 23 2023		
Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com					Tick	et No:	LKK-J00	00057	Vehicle No: SLF2422D		
					Polic	y No:	0		Claim No: 0		
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K						Customer: Teo Yik Hon Vehicle: TOYOTA VOXY 2 X 2016 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 96402541 Email:					
#	Part Name	Description	Quan	tity U	nit Price	Payab	le Amount	Discount	Taxable	Parts Total	
1	REAR BUMPER	Part	1.0)	1,080.40		810.30	270.10	810.30	810.30	
2	REAR BUMPER SIDE HOLDER LH	Part	1.0)	98.50		73.88	24.63	73.88	73.88	
3	TAILLAMP LOWER APRON	Part	1.0)	385.10		288.83	96.28	288.83	288.83	
4	SET REAR BUMPER CLIPS	Part	1.0)	30.00		30.00	0.00	30.00	30.00	
5	SET TAILLAMP LOWER APRON CLIPS	Part	1.0)	20.00		20.00	0.00	20.00	20.00	
									Taxable Value Discount Total Grand Total	1,223.00 391.00 1,223.01	
#	Service	Descrip	Description Q		Unit Pri	ce Pay	able Amour	nt Discount	Taxable	Labour Total	
6	PANEL BEATING, REMOVE AND REFIT PARTS		abour -		300.	.00	300.0	0.00	300.00	300.00	
7	SPRAY PAINTING TO AFFECTED AREA	Labour			300.		300.0			300.00	
8	WIRING CHECK	Labour	ıbour -		30.	.00	30.0	0.00	30.00	30.00	
9	TO REMOVE REVERSE SENSOR	Labour		-	50.	50.00		0.00	50.00	50.00	
		_	•		•			•	Taxable Value	680.00	
									Discount Tota	1 0.00	
Grand Total										680.00	
_							1		<u>I</u>		
Parts Total										1,223.00	
							Labour T	otal		680.00	
							GST Tota	ıl		0.00	
							Grand Total 1,903.			1,903.01	
						Balance			1,903.01		
	ertify that the work has been on dition, with all items / valuab				and that	I have	e taken de	livery of	the vehicle in g	good	

Service Advisor Signature

Customer / Authorized Signatory

Cashier / Authorized Signature