

ADVANCE AUTO GARAGE

23 Kaki Bukit Avenue 4
VICOM KAKI BUKIT INSPECTION CENTRE
#04-01 SINGAPORE 415933
Tel: +65 9007 9247
Email: advanceag@hotmail.com
Reg No: 53395571L

TO	: AIG	DATE	: 7/2/2023
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
VEHICLE DETAILS			
VEHICLE NO	: SNC3556L (2021 OCT)		
VEHICLE MODEL	: CITROEN C4		
CHASSIS NO	: VF73AHNS4MJ779641		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 65.00	\$ 130.00
2	REAR BUMPER <i>Del d</i>	1	\$ 1,356.00	\$ 1,356.00
3	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 85.00	\$ 170.00
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 251.00	\$ 502.00
5	REAR BUMPER TOW COVER <i>new</i>	1	\$ 35.00	\$ 35.00
6	REAR BUMPER LOWER GARNISH <i>Del d</i>	1	\$ 367.00	\$ 367.00
7	REAR BUMPER REINFORCEMENT <i>Del d</i>	1	\$ 595.00	\$ 595.00
8	REAR BUMPER REINFORCEMENT COVER <i>Del d</i>	1	\$ 298.00	\$ 298.00
9	REVERSE SENSOR <i>2 pieces del d</i>	4	\$ 218.00	\$ 872.00
10	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 20.00	\$ 80.00
11	REAR END PANEL <i>3 new</i>	1	\$ 875.00	\$ 875.00
12	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 266.00	\$ 266.00
13	TAILLAMP <i>new</i>	2	\$ 525.00	\$ 1,050.00
14	TAILGATE <i>Del d</i>	1	\$ 2,867.00	\$ 2,867.00
15	TAILGATE LOCK <i>Del d</i>	1	\$ 188.00	\$ 188.00
16	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 179.00	\$ 179.00
17	TAILGATE OUTER GARNISH <i>Del d</i>	1	\$ 454.00	\$ 454.00
18	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 149.00	\$ 149.00
19	CITROEN LOGO <i>2 new</i>	1	\$ 85.00	\$ 85.00
20	CITROEN WORDING <i>new</i>	1	\$ 80.00	\$ 80.00
21	C4 WORDING	1	\$ 82.00	\$ 82.00
22	SPACETOURER WORDING	1	\$ 88.00	\$ 88.00

TOTAL PRICE: \$ 10,768.00

7125
6412.50

LESS 10%
SUB TOTAL PRICE:

\$ 1,076.80
\$ 9,691.20

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>dented</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>gap</i>	1	\$ 20.00	\$ 20.00
5	REAR END PANEL SEALANT <i>gap</i>	1	\$ 60.00	\$ 60.00
6	TAILGATE OUTER GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
7	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
8	REAR CAMERA <i>new</i>	1	\$ 680.00	\$ 680.00
TOTAL :				\$ 930.00

170

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	400	
3	W.RING CHECK	\$ 100.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO REMOVE REAR CAMERA	\$ 100.00	50	
6	TO REMOVE VIDEO RECORDER	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY	\$ 150.00	X	
8	TO SPRAY TUFF COAT	\$ 150.00	X	
9	TO TRANSFER TAILGATE FITTINGS	\$ 450.00	60	
10	TO REPLACE TAILGATE GLASS	\$ 180.00	120	
TOTAL \$		3,430.00		

1160

ESTIMATE REPORT

TOTAL PARTS COST: \$ 10,621.20
TOTAL LABOUR COST: \$ 3,430.00
TOTAL REPAIR COST: \$ 14,051.20

total: 7742.50
L/s: 6.2K

04 days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:
NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

6.2K
04 days