

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123001897/AWY3Q2**Date:** 03/05/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** YJ9433B**Insured Vehicle No :** XE5686C

Date of Loss: 16/02/2023

Nature of Claim:

TP

Claim No: CDMCG23000391

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YJ9433B**

Make &amp; Model: MITSUBISHI CANTER, 3.0 D (M)

Engine No: 4P10B20442

Reg. Date: 06/06/2014 (Man. Year: 2014)

Chassis No: FEB71EA00107

Colour: White

Odometer: 341621 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.50

Rear Tyre Size: 215/75 R17.50

Front Left Side: Noahshine 6 mm

Rear Left Side: Noahshine 6 mm

Front Right Side: Noahshine 6 mm

Rear Right Side: Noahshine 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	37,170.00	7,265.00	29,905.00	80.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,980.00	2,130.00	5,850.00	73.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>45,150.00</b>	<b>9,395.00</b>	<b>35,755.00</b>	<b>79.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>45,150.00</b>	<b>7,500.00</b>	<b>37,650.00</b>	<b>83.39</b>

INSPECTION

Date of Assignment: 20/02/2023

Date Inspected: 28/02/2023 Inspected At:

JL Perfect Autowork Pte Ltd (HQ)

8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 May 2023)	
Parts:	N/A	mitsubishi canter 3.0 d (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YJ9433B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP	O/S Cracked	720.00 FL	*360.00 FL
2	1		*TAILGATE WOODEN	Cracked	2,800.00 FS	*1,800.00 FS
3	4		*TAILGATE HINGE	Not Necessary	720.00 FS	*- FS
4	1		*TAILGATE 60KM STICKER	Necessary	50.00 FS	*15.00 FS
5	1		*SIDE GATE WOODEN RH	Cracked	2,800.00 FS	*1,800.00 FS
6	1		*SIDE GATE HINGE (3 PCS)	Bent (2 PCS ONLY)	540.00 FS	*200.00 FS
7	1		*REAR WHEEL MUDGUARD RH	Not Necessary	680.00 FS	*- FS
8	1		*REAR CARGO BED REAR FRAME	Repair	3,800.00 FS	*- FS
9	6		*REAR CARGO BED BOTTOM BEAMS (WOODEN)	Cracked (4 PCS ONLY)	9,000.00 FS	*2,400.00 FS
10	2		*CARGO BED CHASSIS MEMBER (WOODEN)	Not Necessary	13,000.00 FS	*- FS
11	6		*CARGO BED U CLIP	Not Necessary	1,500.00 FS	*- FS
12	2		*CARGO BED SIDE GATE LOCK	Bent (1 PCS ONLY)	360.00 FS	*80.00 FS
13	1		*CANOPY RAILING	Cracked	1,200.00 FS	*600.00 FS
14	1		*TAIL LAMP BACK SUPPORT BRACKET RH (SPECIAL TYPE)	Bent	180.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)		37,350.00	7,355.00
- List Item Discount on L Items 25.00/25.00% (\$\$)		180.00	90.00
Total Parts (\$\$)		37,170.00	7,265.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT,KNOCK WELD ,CUT,ADJUST ,STRAIGHTEN GRAZE ,ALIGN	New	2,000.00	600.00
2	TO PUTTY ,SPRAY PAINT POLISH WAX	New	2,000.00	600.00
3	BULB CHECKING WIRING	New	180.00	30.00
4	REAR CHASSIS ALIGNMENT	New	200.00	0.00
5	REMOVE AND REFIX CARGO BED	New	2,800.00	800.00
6	REMOVE AND REFIX CANOPY	New	800.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,980.00</b>	<b>2,130.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >