Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 22 Feb 2023 Hiew, Chasin Date:

Preliminary Advice

Vehicle No : SJC4872P **Accident Date** : 11/02/2023 Policy No. Make : AUDI A3 : 2100496254-06

Assignment Date : 21/02/2023 Excess : S\$0.00 Date of Inspection : 20/02/2023 Est. Duration of Repair : 0

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

SINGAPORE 408699

55 UBI ROAD 1

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	171,551.20
Revised Amount	:S\$	Total loss
Check Items (Estimated)	:S\$	
Total	:S\$	

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ 68,000.00 COE / PARF Rebate :S\$ 29,172.00 Salvage Value :S\$

Margin for Repair :S\$ 38,828.00

Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
,)	Other comments :